

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP ALLIANZ
Ezlyng.

ESTIMATE OF REPAIR

Veh# : GBG2610R

Model:

TOYOTA HIACE
(4/7/2017-3/7/2027)

Accident Date : 15/3/2023

Location : UBI AVE 2

3P:

SLJ9903R (ALLIANZ)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tailgate <i>Dented</i>	1950.00	1885	
2	1 pc	Rear tailgate windscreen glass seal <i>3m</i>		100.00	<i>40</i>
3	1 pc	Rear tailgate windscreen glass sealant		80.00	<i>40</i>
4	1 pc	Rear tailgate logo <i>new</i>	77.30		
5	1 pc	Rear tailgate 70km/H sticker <i>3m</i>		25.00	<i>15</i>
6	1 pc	Rear tailgate Toyota Hiace sticker <i>3m</i>		52.00	
7	1 pc	Rear tailgate 1250KG sticker <i>new</i>		80.00	<i>80</i>
8	1 pc	Rear tailgate mechanism lock <i>Dented</i>	263.00	✓	
9	1 pc	Rear tailgate mechanism lock sticker <i>new</i>	70.20	+	
10	1 pc	Rear tailgate inner aluminium panel cover <i>new</i>		280.00	+
11	1 set	Rear tailgate inner aluminium panel cover repair kit <i>new</i>		80.00	+
12	1 pc	Rear tailgate no. plate <i>3m</i>		35.00	+
13	1 pc	Rear tailgate no. plate holder		50.00	+
14	2 pcs	Rear tailgate guide rubber stopped R/L <i>new</i>	57.00	+	
15	2 pcs	Rear tailgate rust proof cover seal <i>new</i>	43.40	+	
16	1 pc	Rear tailgate mechanism lock cover <i>new</i>	98.90	✓	
17	1 pc	Rear bumper <i>Dented</i>	706.00	✓	
18	2 pcs	Rear bumper side retainer R/L <i>Dented</i>	132.20	✓	
19	1 set	Rear bumper clip <i>new</i>		50.00	<i>30</i>
20	1 pc	Rear bumper reverse sensor <i>Dented</i>		280.00	<i>200</i>
21	4 pcs	Rear bumper lower bracket <i>Best</i>	180.40	<i>120</i>	
22	2 pcs	Rear tail lamp R/L <i>Cracked</i>	796.00	✓	
23	2 pcs	Rear tail lamp lower garnish R/L <i>Cracked</i>	314.00	✓	
24	2 pcs	Rear tail lamp lower garnish retainer R/L <i>new</i>	106.00	+	
25	2 pcs	Rear tail lamp lower garnish clip <i>new</i>		60.00	<i>20</i>
26	1 pc	Rear end panel (Outer) <i>3 Dented</i>	563.00	✓	
27	1 pc	Rear end panel (Inner) <i>Repair</i>	926.50	+	
28	1 pc	Rear end panel sealant <i>new</i>		100.00	<i>60</i>
29	1 pc	Rear spare tyre carrier bracket <i>Best</i>	243.10	✓	
30	1 pc	Rear bumper step panel <i>Best</i>	275.00	✓	
31	1 pc	Floor panel aluminium board <i>new</i>		800.00	+
32	2 pcs	Rear end side panel R/L <i>RH Dented</i>	1140.60	<i>385</i>	
33	2 pcs	Rear end side panel rubber stopped R/L <i>new</i>	136.20	X	
34	1 pc	Rear exhaust pipe <i>3m</i>	518.00	+	
35	1 pc	Rear exhaust pipe gasket kit <i>3m</i>	38.00	+	
Sub-Total:			8,634.80	2,072.00	0.00
			25%	0%	0%
After Less %:			6,476.10	2072.00	0.00

		Labour	
1		Labour charge to remove & refix accidental damaged parts & realign affected area.	1,600.00 1000
2		To spray paint on accident affected area.	1,300.00 800
3		To remove & refix rear tailgate windscreen glass.	180.00 120
4		To remove & refix rear side cover, trim garnish & other attachment parts.	120.00 40
5		To remove & refix rear tailgate mechanism & check for function.	80.00 ✓
6		To rust proof accident affected area.	100.00 80
7		To check wiring, lighting & rewire parking sensor.	120.00 80
8		To remove & refix rear exhaust silencer pipe.	120.00 X
		Sub-Total:	3,620.00
		Total:	12,168.10
		After Less 20%:	9,734.48

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call



Adrian L
1/s 20/03/23.
~~06 Days~~
07 Days

List: 5828.50

Less 25%: 4371.37

S.N : 507

Labour : 2200

total: 7078.37

2/s : 5650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: