

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002813/ANCE2**Date:** 05/07/2023**REFERENCE**

Insured/Claimant:	ANG SIEW LAY	Policy No:	1800061143	
Date of Loss:	13/03/2023	Nature of Claim:	OD	Claim No: 3817905473SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ9301P	Engine No:	CYG024449
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G2JN056287
Reg. Date:	11/06/2018 (Man. Year: 2017)	Odometer:	32553 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$116,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,824.00	27,162.16	21,661.84	44.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,672.00	3,272.00	9,400.00	74.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,496.00	30,434.16	31,061.84	50.51
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	61,096.00	30,034.16	31,061.84	50.84
+ GST 8.00/8.00% (S\$)	4,887.68	2,402.73	2,484.95	50.84
Nett Amount (S\$)	65,983.68	32,436.89	33,546.79	50.84

INSPECTION

Date of Assignment:	20/03/2023		
Date Inspected:	17/03/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,677.00 FS	*2,941.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	602.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	151.00 FS	*- FS
4	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	90.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	251.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	1,115.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,262.00 FS	*1,809.60 FS
8	1		*RADIATOR GRILLE COVER	Not Necessary	43.00 FS	*- FS
9	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	158.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	1,360.00 FS	*- FS
11	2		*FRONT BUMPER CHANNEL COVER - LH / RH	Not Necessary	122.00 FS	*- FS
12	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	622.00 FS	*- FS
13	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	543.00 FS	*- FS
14	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	272.00 FS	*- FS
15	4		*FRONT PARKING AID SEAL RING	Not Necessary	6.00 FS	*- FS
16	1		*HORN LOW TONE - LH	Not Necessary	226.00 FS	*- FS
17	1		*HORN HIGH TONE - RH	Not Necessary	226.00 FS	*- FS
18	2		*HORN BRACKET - LH / RH	Not Necessary	112.00 FS	*- FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	280.00 FS	*224.00 FS
20	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	983.00 FS	*- FS
21	2		*HEADLIGHT WASHER COVER CAP - LH / RH	Not Necessary	136.00 FS	*- FS
22	1		*LOCK CARRIER	Not Necessary	1,470.00 FS	*- FS
23	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	27.00 FS	*- FS
24	1		*A/C CONDENSER	Not Necessary	878.00 FS	*- FS
25	1		*CHARGE AIR COOLER	Not Necessary	665.00 FS	*- FS
26	6		*READY-MIX COOLANT	Not Necessary	326.00 FS	*- FS
27	1		*RADIATOR AIR GUIDE - LH	Not Necessary	61.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE - RH	Not Necessary	276.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE COVER - UPPER CENTRE	Not Necessary	34.00 FS	*- FS
30	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	670.00 FS	*- FS
31	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
32	1		*SUNDRIES	Necessary	500.00 FS	*2.72 FS
33	2		*FRONT BUMPER GUIDE PIECE - LH / RH	Not Necessary	89.00 FS	*- FS
34	2		*FRONT BUMPER BRACE - LH / RH	Not Necessary	72.00 FS	*- FS
35	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	31.00 FS	*- FS
36	1		*FRONT BUMPER TOP COVER	Deformed	145.00 FS	*116.00 FS
37	1		*AIR CONDITIONER STICKER	Necessary	24.00 FS	*18.56 FS
38	1		*CAUTION SIGN STICKER	Necessary	17.00 FS	*13.28 FS
39	1		*BONNET	Dented	5,861.00 FS	*4,688.80 FS
40	1		*BONNET ATTACHMENT PARTS	Not Necessary	197.00 FS	*- FS
41	2		*BONNET HINGE - LH / RH	Not Necessary	382.00 FS	*- FS
42	1		*BONNET CATCH HOOK	Not Necessary	165.00 FS	*- FS
43	2		*BONNET LOCK BAR - LH / RH	Not Necessary	119.00 FS	*- FS
44	1		*BONNET CATCH HOOK	Not Necessary	21.00 FS	*- FS
45	2		*BONNET LOCK - LH / RH	Not Necessary	481.00 FS	*- FS
46	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	67.00 FS	*- FS
47	1		*BONNET RELEASE CABLE COVER	Not Necessary	12.00 FS	*- FS
48	1		*BONNET LOCK CABLE	Not Necessary	87.00 FS	*- FS
49	1		*HEADLIGHT MOUNTING - LH / RH	O/s Cracked	280.00 FS	*111.60 FS
50	2		*HEADLIGHT - LH / RH	O/S Cracked / N/S Cut	21,470.00 FS	*17,176.00 FS
51	2		*LIFT CYLINDER - LH / RH	Not Necessary	548.00 FS	*- FS

Report was unsubmitted during this print-out.

7/5/23, 4:12 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LIFT CYLINDER HOSE	Not Necessary	552.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					48,824.00	27,162.16
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,600.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER	New	4,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			12,672.00	3,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >