

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23002818/UWY3E2
Date: 03/04/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30002063295
Claimant Vehicle No :	SNG313U	Insured Vehicle No :	XD9942S
Date of Loss:	15/03/2023	Nature of Claim:	TP
		Claim No:	306858

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG313U		
Make & Model:	BMW 520I, 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A)	Engine No:	A569I522N46B20BE
Reg. Date:	26/02/2010 (Man. Year: 2009)	Chassis No:	WBANT12000CX30440
Colour:	Blue	Odometer:	168636 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,423.75	4,550.64	6,873.11	60.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,200.00	2,440.00	67.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,063.75	5,750.64	9,313.11	61.82
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	15,063.75	4,600.00	10,463.75	69.46
+ GST 8.00/8.00% (S\$)	1,205.10	368.00	837.10	69.46
Nett Amount (S\$)	16,268.85	4,968.00	11,300.85	69.46

INSPECTION

Date of Assignment:	17/03/2023		
Date Inspected:	21/03/2023	Inspected At:	TLM Automobile Pte Ltd (HQ) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts:	143	BMW 520I 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG313U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ASSY LH	Serviceable	685.00 FL	*- FL
2	1		*SIDE MIRROR COVER LH	Cut	190.00 FL	*190.00 FL
3	1		*FRONT DOOR LH	Badly Dented	2,460.00 FL	*1,882.50 FL
4	1		*FRONT DOOR OUTER HANDLE LH	Cut	195.00 FL	*195.00 FL
5	1		*FRONT DOOR BLACK STICKER LH	Necessary	105.00 FL	*105.00 FL
6	1		*FRONT DOOR GLASS OUTER MOULDING LH	Necessary	225.00 FL	*182.40 FL
7	1		*FRONT DOOR GLASS RUN CHANNEL LH	Not Necessary	270.00 FL	*- FL
8	1		*FRONT DOOR INNER LOCK LH	Not Necessary	620.00 FL	*- FL
9	1		*FRONT DOOR GLASS REGULATOR LH	Not Necessary	495.00 FL	*- FL
10	1		*FRONT DOOR GLASS REGULATOR MOTOR LH	Not Necessary	420.00 FL	*- FL
11	1		*FRONT DOOR GLASS GUIDE LH	Not Necessary	150.00 FL	*- FL
12	1		*FRONT DOOR FRAME MOULDING LH	Not Necessary	240.00 FL	*- FL
13	1		*FRONT DOOR INSULATION LH	Not Necessary	150.00 FL	*- FL
14	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	895.00 FL	*- FL
15	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	35.00 FL	*- FL
16	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	250.00 FL	*225.00 FL
17	1		*REAR DOOR LH	Dented	2,450.00 FL	*1,728.25 FL
18	1		*REAR DOOR BLACK STICKER LH	Necessary	105.00 FL	*80.00 FL
19	1		*REAR DOOR LOWER HINGE LH	Not Necessary	185.00 FL	*- FL
20	1		*REAR DOOR GLASS REGULATOR LH	Not Necessary	480.00 FL	*- FL
21	1		*REAR DOOR GLASS REGULATOR MOTOR LH	Not Necessary	450.00 FL	*- FL
22	1		*REAR DOOR WEATHERSTRIP LH	Necessary	255.00 FL	*202.00 FL
23	1		*SIDE SKIRT GARNISH LH	Not Necessary	680.00 FL	*- FL
24	1		*SET SIDE SKIRT GARNISH CLIPS	Not Necessary	35.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	12,025.00	4,790.15
- List Item Discount on L Items 5.00/5.00% (\$\$)	601.25	239.51
Total Parts (\$\$)	11,423.75	4,550.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
2	TO TRANSFER OF BOTH FRONT DOORS AND O/S REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST. @\$120.00	New	240.00	120.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	New	200.00	0.00
4	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT	New	200.00	0.00
5	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,200.00	400.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	600.00
7	TO RUST PROOF AFFECTED AREAS	New	300.00	60.00
Gross Labour Cost (\$\$)			3,640.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >