

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002819/AVCM4**Date:** 03/08/2023**REFERENCE**

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD Policy No: 7220077304
Date of Loss: 09/03/2023 Nature of Claim: OD Claim No: 9587343512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP5199P**
Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) Engine No: DAX054444
Reg. Date: 28/09/2019 (Man. Year: 2019) Chassis No: WAUZZZF5K2073805
Colour: Blue Odometer: 42442 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$160,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,731.00	4,156.64	16,574.36	79.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,552.00	2,402.00	5,150.00	68.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,283.00	6,558.64	21,724.36	76.81
+ GST 8.00/8.00% (S\$)	2,262.64	524.69	1,737.95	76.81
Nett Amount (S\$)	30,545.64	7,083.33	23,462.31	76.81

INSPECTION

Date of Assignment: 20/03/2023
Date Inspected: 16/03/2023 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,536.00 FS	*1,228.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	357.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	45.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	133.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	900.00 FS	*- FS
6	1		*FRONT BUMPER LOWER PANEL	Not Necessary	260.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	691.00 FS	*- FS
8	1		*FRONT BUMPER OUTER GRILLE BAFFLE - LH	Not Necessary	109.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	46.00 FS	*- FS
10	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	272.00 FS	*- FS
11	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
12	1		*HEADLIGHT MOUNTING - LH	Not Necessary	140.00 FS	*- FS
13	1		*HEADLIGHT - LH	Not Necessary	9,226.00 FS	*- FS
14	1		*LIFT CYLINDER - LH	Not Necessary	162.00 FS	*- FS
15	1		*LIFT CYLINDER HOSE	Not Necessary	150.00 FS	*- FS
16	1		*FRONT FENDER - LH	Not Necessary	1,607.00 FS	*- FS
17	1		*FRONT FENDER BRACE - LH	Not Necessary	266.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH	Not Necessary	21.00 FS	*- FS
19	1		*FRONT FENDER CLOSURE PANEL - LH	Not Necessary	37.00 FS	*- FS
20	1		*FRONT FENDER COVER PANEL - LH	Not Necessary	47.00 FS	*- FS
21	1		*FRONT FENDER INNER SHIELD - LH OUTER	Not Necessary	93.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	326.00 FS	*- FS
23	1		*FRONT JOINTED SHAFT COVER - LH	Not Necessary	44.00 FS	*- FS
24	1		*FRONT WHEEL SPOILER	Not Necessary	191.00 FS	*- FS
25	2		*FRONT WHEEL COVER - LH / RH	N/s Cut/ O/s Necessary	1,504.00 FS	*1,202.40 FS
26	1		*FRONT ALUMINIUM RIM - LH	Cut	2,153.00 FS	*1,722.40 FS
27	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*3.04 FS
28	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 20,731.00 4,156.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,800.00	950.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,552.00	2,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >