

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002826/AVY3E2**Date:** 05/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBM669D**Insured Vehicle No :** YP2528B

Date of Loss: 13/03/2023

Nature of Claim: TP

Claim No: CDMCG23000633

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBM669D**

Make & Model: NISSAN NV350 CARAVAN, 2.0 DX (A)

Engine No: QR20027480R

Reg. Date: 31/10/2022 (Man. Year: 2022)

Chassis No: VR2E26159508

Colour: Blue

Odometer: 9060 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15C

Rear Tyre Size: 195/80 R15C

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,598.45	1,550.99	2,047.46	56.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	730.00	770.00	51.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,098.45	2,280.99	2,817.46	55.26
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	5,098.45	1,800.00	3,298.45	64.70
+ GST 8.00/8.00% (S\$)	407.88	144.00	263.88	64.70
Nett Amount (S\$)	5,506.33	1,944.00	3,562.33	64.70

INSPECTION

Date of Assignment: 17/03/2023

Date Inspected: 20/03/2023 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Mar 2023)	
Parts:	N/A	NISSAN NV350 CARAVAN 2.0 DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBM669D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	571.90 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	329.00 FL	*- FL
3	1		*FRONT GRILLE	Cracked	565.00 FL	*565.00 FL
4	1		*FRONT GRILLE LOGO EMBLEM	Necessary	94.00 FL	*94.00 FL
5	1		*FRONT RH CORNER PANEL	Dented	534.60 FL	*534.60 FL
6	1		*FRONT RH DOOR	Repair	1,156.00 FL	*- FL
7	1		*FRONT RH DOOR CHECKER	Not Necessary	53.10 FL	*- FL
8	1		*FRONT RH DOOR HINGE (LOWER)	Not Necessary	54.70 FL	*- FL
9	1		*FRONT RH DOOR HINGE (TOP)	Not Necessary	54.70 FL	*- FL
10	1		*FRONT RH HEADLAMP	Cracked	457.50 FL	*457.50 FL
11	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT RH DOOR COMPANY DETAIL STICKER	Necessary	25.00 FS	*25.00 FS
13	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
14	1		*SET FRONT RH HEADLAMP CLIPS	Necessary	30.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,985.50	1,716.10
- List Item Discount on L Items 10.00/10.00% (\$)	387.05	165.11
Total Parts (\$)	3,598.45	1,550.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)	New	80.00	30.00
2	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	New	120.00	0.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	300.00
Gross Labour Cost (\$\$)			1,500.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >