

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS23002830/UPA3Q2**Date:** 27/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002822734-01
<b>Claimant Vehicle No :</b>	SLF8335H	<b>Insured Vehicle No :</b>	SMV4782E
Date of Loss:	16/03/2023	Nature of Claim:	TP
		Claim No:	202332006374

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLF8335H</b>	Engine No:	2ARH689745
Make & Model:	TOYOTA VELLFIRE, 2.5 Z (A)	Chassis No:	AGH300054577
Reg. Date:	13/09/2016 (Man. Year: 2015)	Odometer:	106802 km
Colour:	Purple		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	RIVO 6 mm	Rear Left Side:	RIVO 6 mm
Front Right Side:	RIVO 6 mm	Rear Right Side:	RIVO 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,512.20	5,788.35	11,723.85	66.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,990.00	1,340.00	40.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,842.20</b>	<b>7,778.35</b>	<b>13,063.85</b>	<b>62.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,900.00</b>		
<b>(S\$)</b>	20,842.20	5,900.00	14,942.20	71.69
<b>+ GST 8.00/8.00% (S\$)</b>	1,667.38	472.00	1,195.38	71.69
<b>Nett Amount (S\$)</b>	<b>22,509.58</b>	<b>6,372.00</b>	<b>16,137.58</b>	<b>71.69</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,974.00</b>		

**INSPECTION**

Date of Assignment:	20/03/2023	
Date Inspected:	30/03/2023	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 Z (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF8335H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,866.10 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	99.50 F	*99.50 FL
3	1		*TAILGATE	Badly Dented	2,650.20 F	*2,415.11 FL
4	1		*TAILGATE VELLFIRE EMBLEM	Serviceable	105.10 F	*- FL
5	1		*TAILGATE WEATHERSTRIP	Twisted	388.90 F	*388.90 FL
6	1		*TAILGATE INNER LOCK	Damaged / Shorted	650.20 F	*650.20 FL
7	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	955.80 F	*955.80 FL
8	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
9	2		*TAILGATE REFLECTORS	Not Necessary	1,378.20 F	*- FL
10	1		*TAILGATE OUTER GARNISH	Not Necessary	855.20 F	*- FL
11	1		*REAR BUMPER	Dented	1,450.00 F	*1,315.22 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	170.00 F	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*REAR BUMPER TOW COVER	Not Necessary	48.00 F	*- FL
15	2		*REAR BUMPER PDC SENSORS	Malfunction	530.00 F	*530.00 FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	196.00 F	*- FL
17	1		*REAR END PANEL	Dented	911.20 F	*911.20 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	245.20 F	*245.20 FL
19	2		*TAILLAMPS	Not Necessary	1,900.20 F	*- FL
20	2		*TAILLAMP LOWER GARNISHS	Repair	1,300.20 F	*- FL
21	1		*REAR ANTENNA SENSOR	Not Necessary	226.20 F	*- FL
22	1		*REAR BUZZER SENSOR	Not Necessary	210.50 F	*- FL
23	1		*REAR FLOOR PANEL	Repair	1,125.50 F	*- FL
24	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
25	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
26	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,512.20	7,691.13
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,902.78
Total Parts (\$\$)	17,512.20	5,788.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	700.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
<b>Gross Labour Cost (S\$)</b>			<b>3,330.00</b>	<b>1,990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >