

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002832/UNP3Q2**Date:** 03/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00232822203
Claimant Vehicle No :	SJP1902M	Insured Vehicle No :	SJE9435A
Date of Loss:	16/03/2023	Nature of Claim:	TP
		Claim No:	SNM23D202037/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP1902M	Engine No:	1NZX874127
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305103598
Reg. Date:	13/03/2009 (Man. Year: 2009)	Odometer:	271060 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,631.20	1,351.62	4,279.58	76.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	900.00	1,770.00	66.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,301.20	2,251.62	6,049.58	72.88
Approved Total (Overridden) (\$\$)		1,800.00		
Nett Amount (\$\$)	8,301.20	1,800.00	6,501.20	78.32

INSPECTION

Date of Assignment:	17/03/2023	HH MOTOR TRADING (HQ) BLK 3012 BEDOK NORTH AVE 4 #01-2054 BEDOK INDUSTRIAL PARK E Singapore 489978
Date Inspected:	21/03/2023 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP1902M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Cut	531.30 F	*481.10 FL
2	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	397.00 F	*- FL
3	1		*FRONT BUMPER RETAINER LH	Necessary	65.90 F	*65.90 FL
4	1		*FRONT BUMPER BRACKET LH	Not Necessary	68.20 F	*- FL
5	1		*FRONT BUMPER FOGLAMP COVER LH	Not Necessary	110.40 F	*- FL
6	1		*FRONT HEADLAMP LH	Not Necessary	497.10 F	*- FL
7	1		*FRONT FENDER LH	Repair	727.10 F	*- FL
8	1		*FRONT FENDER SPLASH GUARD LH	Torn	124.10 F	*124.10 FL
9	1		*FRONT BUMPER LOGO	Not Necessary	75.20 F	*- FL
10	1		*FRONT SHOCK ABSORBER LH	Not Necessary	415.20 F	*- FL
11	1		*FRONT SHOCK ABSORBER MOULDING LH	Not Necessary	210.10 F	*- FL
12	1		*FRONT WHEEL HUB LH	No such part	465.20 F	*- FL
13	1		*FRONT LOWER ARM LH	Bent	435.10 F	*435.10 FL
14	1		*FRONT WHEEL BEARING LH	Necessary	185.20 F	*185.20 FL
15	1		*FRONT KNUCKLE ASSEMBLY LH	Bent	404.10 F	*404.10 FL
16	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
17	1		*SET FRONT FENDER SPLASH GUARD CLIPS	Necessary	40.00 FS	*40.00 FS
18	1		*SIDE DOOR WIRE HARNESS LH	Not Necessary	180.00 FS	*- FS
19	1		*FRONT ALLOY RIM LH	Repair	280.00 FS	*- FS
20	1		*FRONT TYRE LH	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,631.20	1,775.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	423.88
Total Parts (\$\$)	5,631.20	1,351.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ANTI-RUST TREATMENT	New	120.00	0.00
2	TO CONDUCT 4 WHEEL ALIGNMENT	New	150.00	80.00
3	UNDER-CARRIAGE REPAIR WORKS (INCLUDING REMOVING AND INSTALLING OF SHOCK ABSORBER ,LOWER ARM ,KNOCKLE ARM ,DRIVE SHAFT ,STEERING RACK ,LINKS AND ALL NECESSARY)	New	450.00	120.00
4	LABOUR TO REMOVE AND REPLACE ,KNOCK AND JACK FRONT PANEL WHEEL ,HOUSING ,INCLUDING REPOSITIONING OF REPLACED PARTS	New	950.00	300.00
5	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,670.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >