

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23002833/UNY3Q2**Date:** 11/04/2023**REFERENCE**

Insured/Claimant:	TAY MIN WEI	Policy No:	SP2001779358-01	
Date of Loss:	15/03/2023	Nature of Claim:	OD	Claim No: 202332006340

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB6031U		
Make & Model:	M.G. HS, 1.5 (A)	Engine No:	15E4E8AGM4010008
Reg. Date:	31/08/2021 (Man. Year: 2021)	Chassis No:	LSJA24U9XMN081109
Colour:	Black	Odometer:	24551 km
Engine Capacity:	1490 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,931.60	10,663.80	267.80	2.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,580.00	670.00	29.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,181.60	12,243.80	937.80	7.11
- Excess (\$\$)	600.00	1,100.00	-500.00	-83.33
(\$\$)	12,581.60	11,143.80	1,437.80	11.43
+ GST 8.00/8.00% (\$\$)	1,006.53	891.50	115.03	11.43
Nett Amount (\$\$)	13,588.13	12,035.30	1,552.83	11.43

INSPECTION

Date of Assignment:	18/03/2023	Present Location:	Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected:	20/03/2023	Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2023)
Parts:	M1-SUV	M.G. HS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB6031U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Distorted	900.00 F	*900.00 F
2	1		*FRONT BUMPER SIDE RETAINER (WCP)	O/s Bent / N/s Not Necessary	116.00 F	*58.00 F
3	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
4	1		*FRONT BUMPER RIVET	Necessary	50.00 FS	*50.00 FS
5	1		*FRONT BUMPER TOW COVER (WCP)	Torn	75.00 F	*75.00 F
6	1		*FRONT BUMPER LOWER GARNISH (WCP)	Distorted	385.00 F	*385.00 F
7	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	650.00 F	*650.00 F
8	1		*FRONT BUMPER TOP (WCP)	Dented / Deformed	290.00 F	*290.00 F
9	1		*O/S FOGLAMP CHROME (WCP)	Cracked	125.00 F	*125.00 F
10	1		*RADIATOR GRILLE ASSY (WCP)	Cracked	850.00 F	*850.00 F
11	1		*LOGO EMBLEM (WCP)	Not Necessary	90.00 F	*- F
12	1		*RADIATOR GRILLE BRACKET (WCP)	Cracked	130.00 F	*260.00 F
13	1		*O/S HEADLAMP (WCP)	Holder Cracked	2,200.00 F	*2,200.00 F
14	1		*RADIATOR SUPPORT PANEL (WCP)	Cracked	800.00 F	*800.00 F
15	1		*RADIATOR SUPPORT PANEL TOP COVER (WCP)	Not Necessary	180.00 F	*- F
16	1		*RADIATOR SUPPORT PANEL TOP COVER STICKER	Not Necessary	50.00 FS	*- FS
17	1		*BONNET (WCP)	Dented / Buckled	1,850.00 F	*1,850.00 F
18	1		*BONNET CHASSIS STICKER	Necessary	50.00 FS	*50.00 FS
19	1		*O/S FRONT FENDER (WCP)	Bent / Buckled	750.00 F	*750.00 F
20	1		*O/S RAD AIR GUIDE (WCP)	Torn	80.00 F	*80.00 F
Supplementary #1						
21	1		*O/S FOGLAMP (WCP)	Cracked	285.00 F	*285.00 F
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					9,956.00	9,708.00
+ Margin on L,N Items 10.00/10.00% (S\$)					975.60	955.80
Total Parts (S\$)					10,931.60	10,663.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	TO VAC, REOIL AND REGAS AIRCON	New	120.00	100.00
3	TO DIAGNOSE, REPROGRAM AND CLEAR CODE	New	280.00	60.00
4	LABOUR/PANEL BEATING	New	800.00	600.00
5	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (S\$)			2,250.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >