

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002843/UQP3E2**Date:** 09/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00049032200
Claimant Vehicle No :	SJH8986S	Insured Vehicle No :	GBD614J
Date of Loss:	14/03/2023	Nature of Claim: TP	Claim No: SNM23D201966/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH8986S	Engine No:	G4FGJU137712
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU631414
Reg. Date:	23/02/2018 (Man. Year: 2018)	Odometer:	127559 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,384.80	1,046.40	1,338.40	56.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	930.00	1,010.00	52.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,324.80	1,976.40	2,348.40	54.30
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	4,324.80	1,550.00	2,774.80	64.16
+ GST 8.00/8.00% (S\$)	345.98	124.00	221.98	64.16
Nett Amount (S\$)	4,670.78	1,674.00	2,996.78	64.16

INSPECTION

Date of Assignment:	17/03/2023		
Date Inspected:	17/03/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH8986S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	460.00 FL	*460.00 FL
2	2		*REAR BUMPER SIDE HOLDER -LH/RH	Not Necessary	88.00 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	295.00 FL	*- FL
5	3		*REAR BUMPER REINFORCEMENT BRACKET TOP -LH/RH	Not Necessary	36.00 FL	*- FL
6	3		*REAR BUMPER REINFORCEMENT BRACKET (LOWER) -LH/RH	Not Necessary	36.00 FL	*- FL
7	1		*REAR BUMPER LOWER LIP (BLACK)	Repair	251.00 FL	*- FL
8	2		*REAR BUMPER REFLECTORS -LH/RH	Not Necessary	84.00 FL	*- FL
9	1		*REAR BOOT ELNATRA WORDINGS	Necessary	49.00 FL	*49.00 FL
10	1		*REAR BOOT RUBBER	Not Necessary	93.00 FL	*- FL
11	1		*REAR END PANEL	Repair	455.00 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	60.00 FL	*- FL
13	1		*SET REAR BUMPER SENSOR	Malfunction	220.00 FS	*200.00 FS
14	1		*REAR BUMPER CENTER LAMP	Not Necessary	200.00 FS	*- FS
15	1		*REAR BUMPER LOWER SPOILER	Cracked	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,776.00	1,158.00
- List Item Discount on L Items 20.00/20.00% (\$)	391.20	111.60
Total Parts (\$)	2,384.80	1,046.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	800.00	400.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	400.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO REMOVE,REPLACE /REFIT REAR BUMPER SENSOR	New	100.00	50.00
5	TO REMOVE ,REFIX REAR GARNISH	New	150.00	60.00
6	TO TUFF -KOTE	New	60.00	0.00
Gross Labour Cost (\$\$)			1,940.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >