



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 169722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004587879	Date of Loss:	15/03/2023
Vehicle Reg. No.:	SKX258S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIAO BANG XIONG		

Make/Model:	BMW 318i, 1.5 SEDAN LED NAV (A)	Vehicle Reg. Date:	17/08/2015
Vehicle Colour:	SILVER	Chassis No:	WBA8E32070K497522
Engine No:	F2361184B38B15A		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	19,422.70
Labour	45.00
Paintwork Labour	2,640.00
Towing	0.00
	0.00
Gross Total (\$\$)	22,107.70
+ GST 8.00% (\$\$)	1,768.62
Nett Amount (\$\$)	23,876.32

This claim is handled by: **KEONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2023)
 Parts: 143 BMW 318i 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKX258S)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>bt</i>			
2	2		*BONNET HINGE L+R <i>X</i>	0.00	0.00	*1,500.00 F
3	2		*BONNET LOCK LOWER L+R <i>?</i>	0.00	0.00	*270.00 F
4	2		*BONNET LOCK TOP L+R <i>?</i>	0.00	0.00	*240.00 F
5	2		*BONNET LOCK TOP COVER L+R <i>?</i>	0.00	0.00	*90.00 F
6	1		*BONNET RUBBER <i>an</i>	0.00	0.00	*30.00 F
7	1		*FRONT LOGO <i>an</i>	0.00	0.00	*90.00 F
8	2		*FRONT GRILLE L+R <i>can</i>	0.00	0.00	*110.00 F
9	2		*HEADLAMP L+R <i>can</i>	0.00	0.00	*250.00 F
10	2		*HEADLAMP BRACKET L+R <i>?</i>	0.00	0.00	*5,200.00 F
11	2		*HEADLAMP PANEL L+R <i>requir</i>	0.00	0.00	*56.00 F
12	2		*HEADLAMP CLIPS <i>an</i>	0.00	0.00	*400.00 F
13	1		*SUPPORT TOP PANEL <i>bt</i>	0.00	0.00	*24.00 F
14	1		*SUPPORT AIR DUCT TOP <i>?</i>	0.00	0.00	*275.00 F
15	1		*SUPPORT AIR DUCT LOWER <i>?</i>	0.00	0.00	*255.00 F
16	1		*SUPPORT V BAR <i>?</i>	0.00	0.00	*210.00 F
17	1		*FRONT FENDER RH <i>bt</i>	0.00	0.00	*150.00 F
18	1		*FRONT FENDER COWLING RH <i>de</i>	0.00	0.00	*770.00 F
19	10		*FRONT FENDER COWLING RIVETS <i>an</i>	0.00	0.00	*210.00 F
20	1		*FRONT FENDER BRACKET RH	0.00	0.00	*30.00 F
21	1		*FRONT BUMPER <i>form</i>	0.00	0.00	*58.00 F
22	1		*FRONT BUMPER TOW COVER RH <i>mis</i>	0.00	0.00	*2,100.00 F
23	1		*FRONT BUMPER LOWER GRILLE <i>X</i>	0.00	0.00	*69.00 F
24	1		*FRONT BUMPER WASHER COVER RH <i>mis</i>	0.00	0.00	*180.00 F
25	1		*FRONT BUMPER WASHER JET <i>?</i>	0.00	0.00	*70.00 F
26	1		*FRONT BUMPER SPONGE <i>X</i>	0.00	0.00	*155.00 F
27	1		*FRONT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*90.00 F
28	2		*FRONT BUMPER REINFORCEMENT BRACKET L+R <i>X</i>	0.00	0.00	*490.00 F
29	2		*FRONT BUMPER BRACKET L+R <i>an</i>	0.00	0.00	*280.00 F
30	2		*FRONT BUMPER RETAINER L+R <i>an</i>	0.00	0.00	*70.00 F
31	10		*FRONT BUMPER RIVET <i>an</i>	0.00	0.00	*60.00 F
32	1		*A/C CONDENSER <i>?</i>	0.00	0.00	*30.00 F
33	1		*RADIATOR <i>?</i>	0.00	0.00	*1,270.00 F
34	1		*RADIATOR TOP HOSE <i>X</i>	0.00	0.00	*980.00 F
35	1		*RADIATOR BY PASS HOSE <i>X</i>	0.00	0.00	*210.00 F
36	2		*RADIATOR SIDE BRACKET L+R <i>X</i>	0.00	0.00	*115.00 F
37	2		*RADIATOR TOP MOUNTING L+R <i>X</i>	0.00	0.00	*200.00 F
38	2		*RADIATOR TOP BRACKET L+R <i>X</i>	0.00	0.00	*40.00 F
39	1		*RADIATOR LOWER HOSE <i>X</i>	0.00	0.00	*50.00 F
40	1		*AIR CLEANER BOX ASSY <i>an</i>	0.00	0.00	*180.00 F
41	1		*AIR DUCT <i>?</i>	0.00	0.00	*680.00 F
42	1		*AIR HOSE <i>X</i>	0.00	0.00	*55.00 F
				0.00	0.00	*65.00 F

F=Franchise part.

Sub Total (\$\$)	17,657.00
+ Margin on L,N Items 10.00% (\$\$)	1,765.70
Total Parts (\$\$)	19,422.70

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1 FRONT NUMBER PLATE *ca*~~35~~ 45.00

Sub Total (\$\$)

45.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TOWING CHANGES - TO BE CONFIRM		
2	TO CUT & WELD SUPPORT PANEL, TO REPAIR FRONT FENDER L+R, FRONT CHASSISMEMBER FRONT DOOR L+R, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	700
3	TO SPRAY AFFECTED AREAS, FRONT DOOR L+R, FRONT FENDER L+R, BONNET, SUPPORT PANEL, FRONT BUMPER & AFFECTED AREAS	New	650 1,000.00
4	TO REMOVE & REFIX A/C CONDENSOR, ELECTRIC FAN, HOSE, PIPE, VACUUM & REFILLING GAS	New	650 1,100.00
5	TO REMOVE & REFIX AIR CLEANER BOX, RADIATOR & OTHER ATTACHMENT PARTS	New	100? 120.00
6	TO DIAGNOSTIC & PROGRAMMING WERE NECESSARY	New	80 60.00
		New	150 300.00
Gross Labour Cost (\$\$)			2,640.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rane
Hq 90010068

8 days

4/8

26/03/23 @ 1650

EXCESS: 1100

Revert

Resurvey after repair