4/20/23, 12:34 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23002846/KWP3Q2

20/04/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00057032200

Claimant Vehicle

SMS5003E

Insured

GBJ5287E

No:

Vehicle No:

Date of Loss:

17/03/2023

Nature of Claim: TP

Claim No:

SNM23D202040/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMS5003E

Make & Model:

JAGUAR XE, 2.0 I4P TSS (A) 23/12/2016 (Man. Year: 2016) Engine No: Chassis No: 015324055758204PT

Reg. Date: Colour:

Metallic Dark Blue

Odometer:

SAJAB4AG3HA967968 107233 km

Engine Capacity:

1999 cc

Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable): Yes

Pre-accident Condition:

Yes

Handbrake (Serviceable): **CONDITION OF TYRES**

Engine Modification: Yes

No

245/40Z R18

Front Tyre Size: Front Left Side:

245/40Z R18 Pirelli 7 mm

Rear Tyre Size: Rear Left Side:

Pirelli 7 mm

Front Right Side:

Pirelli 7 mm

Rear Right Side:

Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,925.50	4,709.43	1,216.07	20.52
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,280.00	1,060.00	1,220.00	53.51
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gro	ss Total (S\$)	8,205.50	5,769.43	2,436.07	29.69
Approved Total (Ove	rridden) (S\$)		4,600.00		
Nett	Amount (S\$)	8,205.50	4,600.00	3,605.50	43.94

INSPECTION

Date Inspected:

Adjuster:

Date of Assignment:

26/03/2023

27/03/2023 Inspected At:

Tropical Tech Automobile Services (HQ)

BLK 5032 ANG MO KIO AVENUE 3, #01-303 **INDUSTRIAL PARK 2**

Singapore 569535

Estimated Period of Repair:

4.0 days

KENNETH KONG

Manager:

XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

4/20/23, 12:34 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Apr 2023)

Parts: 143 JAGUAR XE 2.0 I4P TSS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS5003E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented / Warped	2,112.00 FL	*2,056.70 FL
2	1		*REAR BOOT EMBLEM WITH JAGUAR DESIGNTION	Dented	267.00 FL	*142.00 FL
3	1		*REAR BOOT XE DESIGNATION	Necessary	127.00 FL	*80.00 FL
4	1		*REAR BOOT 2.0 DESIGNATION	Necessary	151.00 FL	*80.00 FL
5	1		*REAR BUMPER	Buckled / Dented	1,774.00 FL	*1,774.00 FL
6	4		*REAR BUMPER PARKTRONIC SENSOR	Shorted (2 PCS ONLY)	628.00 FL	*314.00 FL
7	1		*REAR BUMPER TOWING COVER	Serviceable	59.00 FL	*- FL
8	1		*REAR BUMPER LIP	Dented / Cut	835.00 FL	*786.00 FL
9	2		*REAR BUMPER SIDE RETAINER	Serviceable	348.00 FL	*-FL
10	1		*REAR BUMPER FRAME (CENTRE)	Serviceable	244.00 FL	*- FL
11 E-Er	1	nort S-Sno	*REAR LICENSE SMART PLATE & CASING Nett. L=ListItemDisc.	Serviceable	35.00 FS	*-FS
1 -1 16	IIIOIIISC	part. 0-0pc	Nett. L-Listite IIIDisc.	Sub Total (S\$)	6,580.00	5,232.70
	- List Item Discount on L Items 10.00/10.00% (S\$)			654.50	523.27	
				Total Parts (S\$)	5,925.50	4,709.43
					,	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	ur Items			
1	HEAT/WELD/BEATING/PULL/STRAIGHTEN /ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	900.00	450.00
2	REMOVE AND TRANSFER REAR BOOT NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
3	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
4	REMOVE AND REFIT REAR BOOT ,REAR BOOT EMBLEM WITH JAGUAR DESIGNATION ,REAR BOOT XE DESIGNATION ,REAR BOOT 2.0 DESIGNATION,REAR BUMPER ,REAR BUMPER PARKING SENSOR ,REAR BUMPER TOWING COVER ,REAR BUMPER LIP ,REAR BUMPER SIDE RETAINERS,REAR BUMPER FRAME }	New	0.00	0.00
5	DIAGNOSTIC AND RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT	New	100.00	60.00
6	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS	New	80.00	20.00
7	UNDER COATING ON REAR DAMAGED PORTION	New	200.00	30.00
8	PUTTY /PRIMER APPLICATION ,SPRAY PAINTING REAR BOOT ,REAR BUMPER ,REAR BUMPER PARKING SENSORS,REAR BUMPER TOWING COVER	New	1,000.00	500.00
	Gross Labour	r Cost (S\$)	2,280.00	1,060.00
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >