



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 8707J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEEP CUT	988.00	781.00
1	FRONT BUMPER SIDE RETAINER N/S	NECESSARY	32.00	32.00
1	FRONT BUMPER FOG LAMP N/S	NOT NECESSARY	305.00	-
1	FRONT BUMPER FOG LAMP COVER N/S	GRAZED	145.00	127.00
1	SET FRONT BUMPER CLIPS	NECESSARY	42.00	42.00
1	HEADLAMP N/S	HOLDER CRACKED	1,075.00	1,075.00
1	FRONT FENDER N/S	NOT NECESSARY	484.00	-
1	FRONT FENDER INNER SHIELD N/S	NOT NECESSARY	162.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NOT NECESSARY	40.00	-
	LESS 10% DISCOUNT		-	-205.70
			3,273.00	1,851.30
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		600.00	200.00
	TO PUTTY & SPRAY PAINTING.		600.00	200.00
			1,450.00	420.00
	GRAND TOTAL		4,723.00	2,271.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00

Report Ref No. CS/GAI23002851/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.