



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 2223P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	1,495.00	-
1	BOOTLID 'PEUGEOT' EMBLEM	NECESSARY	58.00	58.00
1	BOOTLID '308' EMBLEM	NECESSARY	68.00	68.00
1	BOOTLID CENTRE LOGO	NECESSARY	128.00	128.00
1	REAR BUMPER	BADLY DENTED / TORN	1,320.00	950.00
1	REAR PANEL REINFORCEMENT	TO REPAIR SEE LABOUR	700.00	-
4	REAR BUMPER SENSOR @\$250.00	NOT NECESSARY	1,000.00	-
8	REAR BUMPER CLIPS @\$8.00	NECESSARY	64.00	64.00
	LESS 10% DISCOUNT		-	-126.80
			4,833.00	1,141.20
<u>LABOUR</u>				
	REMOVE THE NECESSARY AFFECTED PARTS STRAIGHTEN REAR PANEL, REAR PANEL REINFORCEMENT AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR PANEL REINFORCEMENT.		1,400.00	300.00
	CHECK ELECTRICAL.	NOT NECESSARY	20.00	-
	REMOVE AND REFIT BOOTLID COMPONENTS.	NOT NECESSARY	150.00	-
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		900.00	400.00
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	200.00	-
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	40.00
	REWIRE REAR PORTION.	NOT NECESSARY	50.00	-
			2,820.00	740.00
GRAND TOTAL			7,653.00	1,881.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS3/SMR23002853/Rwy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.