

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers
227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

SOH HAN TIONG, KELTONN

**C/O 1 Soon Lee Street, #05-22, Pioneer
Centre, Singapore 627605**

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : 11 March 2023
Assignment Date : 20 March 2023
Inspection Date : 20 March 2023
Our Reference No. : PAS/J1/230129/TP

Inspection Report Date : 03 April 2023

Name of Workshop:

J ONE CAR SPRAY SPECIALIST

Inspection Address :

**1 Soon Lee Street, #05-22, Pioneer Centre,
Singapore 627605**

PARTICULARS OF VEHICLE

Registration No.	: SNA2223P	Mileage	: 81490	Km/h
Make/Model	: PEUGEOT 308 SW ALLURE PURETECH 1.2 A/T 2WD S/R	Radio/Casette	: Fitted	
Yr of Manuf/Regn	: 24 Nov 2017	CD Disc Player	: Fitted	
Carrying Capacity	: 4 Seater	Air Conditioner	: Fitted	
Chassis No.	: VF3LRHNYWHS178482	Clock	: Fitted	
Engine No.	: 10XTA40738380	Seat Belt	: Fitted	
Colour	: Pearl White	Wing Mirror	: Fitted	
Class	: Passenger (Private)	Other Accessories	: Fitted	

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent :
Eng Modifications : None

VEHICLE VALUE

Market Value : -
Wreck Value (Parf) : -

TYRE SIZE & CONDITION

Front N/s Size	: 225/45R17	80 %
Make	: FALKEN	
Rear N/s size	: 225/45R17	80 %
Make	: FALKEN	
Spare Size	: 225/45R17	80 %
Make	: FALKEN	

Front O/s Size	: 225/45R17	80 %
Make	: FALKEN	
Rear O/sSize	: 225/45R17	80 %
Make	: FALKEN	
Spare Size		
Make		
Jack & Tools	: Intact/Missing	

Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO. : SNA 2223 P

APPENDIX A



POINT OF IMPACT

(Diagram A)

FRONT

(Diagram B)

FRONT

(Diagram C)


FRONT

(Diagram D)


FRONT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its Rear Portion (see Diagram B)




NEAR SIDE
OFF SIDE



NEAR SIDE
OFF SIDE



NEAR SIDE
OFF SIDE



NEAR SIDE
OFF SIDE

GENERAL DESCRIPTION OF DAMAGES

Parts damaged were: The bootlid, rear panel and reinforcement, rear bumper were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 20/03/2023 & our report is here with enclosed for your perusal.

The Repairs Estimate submitted by M/s J ONE CAR SPRAY SPECIALIST as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$4,000.00 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Spares Parts	4833	00	3044	70
Towing Charges	X	X	X	X
PB Labour Charges	1400	00	980	00
Others Misc Charges	520	00	400	00
Paintwork	900	00	600	00
Total	\$ 7653	00	\$ 5024	70

Under normal circumstances, the duration of repairs should not exceed Five(05) days including Pre-Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame.

Attached photographs taken during inspection Forty - Three(43) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 21/03/2023, we examined the extent of damages.
3. On 24/03/2023, we examined the repaired vehicle.

Yours Faithfully,

TF PHILIP FOO
AIMI CAE, AMIMI
AIAME, AMSAE-A
Licensed Appraiser/Adjuster



Inspection Report Date: 03 April 2023

VEHICLE REGN NO : SNA 2223 P
 OUR REFERENCE : PAS/J1/230129/TP
 INSPECTION REPORT DATE : 3-Apr-23

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO : 1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount \$ cts	Recommendation / Revised Amount \$ cts
<u>PARTS SUPPLY - LIST ITEMS</u>					
1	1pc	Bootlid repair	Dented/Cracked	1495.00	1495.00 X R
2	1pc	Bootlid 'Peugeot' emblem	Necessary	58.00	58.00 ✓
3	1pc	Bootlid '308' emblem	Necessary	68.00	68.00 ✓
4	1pc	Bootlid centre logo	Necessary	128.00	128.00 ✓
5	1pc	Rear bumper	Badly Dented/Torn	1320.00	1320.00 950
6	1pc	Rear panel reinforcement	Dented	700.00	Repair
7	4pcs	Rear bumper sensor@\$250	Centre O/s Dented/Jammed	1000.00	250.00 X m
8	3pcs	Rear bumper clips@\$8	Necessary	64.00	64.00 ✓
			1268	4833.00	3383.00
		Less: 10% discount	10%	-	338.30
			1141.20	4833.00	3044.70
<u>LABOUR & MISC. CHARGES</u>					
1		Remove the necessary affected parts straighten rear panel, rear panel reinforcement and replace parts	1141.20 740.00 1881.20	1400.00	980.00 300
2		Check electrical	20%	20.00	20.00 X
3		Remove and refit bootlid components	1504.96	150.00	120.00 X
4		Putty and Spraypaint on all affected parts	45-\$1,500/3days	900.00	600.00 400
5		Remove and refit rear windscreen		200.00	150.00 X
6		Remove and refit rear bumper sensors		100.00	80.00 40
7		Rewire rear portion		50.00	30.00 X 740
		Note: Recommended lump sum repair at \$4,000.00nett			
SUB / GRAND TOTAL				7653.00	5024.70

PRECISION APPRAISAL SERVICES

Ce

