

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23002856/ATWY3M4**Date:** 19/05/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001897035
<b>Claimant Vehicle No :</b>	SMM7274H	<b>Insured Vehicle No :</b>	FBQ9119U
Date of Loss:	18/03/2023	Nature of Claim:	TP
		Claim No:	307206

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMM7274H</b>	Engine No:	3A92UDS3386
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH004413
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	102424 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,259.03	1,052.67	1,206.36	53.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	960.00	1,490.00	60.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,709.03</b>	<b>2,012.67</b>	<b>2,696.36</b>	<b>57.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>(S\$)</b>	4,709.03	1,600.00	3,109.03	66.02
<b>+ GST 8.00/8.00% (S\$)</b>	376.72	128.00	248.72	66.02
<b>Nett Amount (S\$)</b>	<b>5,085.75</b>	<b>1,728.00</b>	<b>3,357.75</b>	<b>66.02</b>

INSPECTION

Date of Assignment: 21/03/2023

Date Inspected: 20/03/2023

Inspected At:

ONE GARAGE PTE LTD  
8 KAKI BUKIT AVENUE 4  
#03-33 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

Estimated Period of Repair: 3.0 days

**Adjuster:** XinYu**Manager:** MOHD TAUFIKH BIN HAMID

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 May 2023)	
<b>Parts:</b>	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM7274H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	765.30 FL	*765.30 FL
2	1		*REAR BUMPER SIDE HOLDER	Damaged	35.60 FL	*35.60 FL
3	1		*REAR BUMPER REFLECTOR	Not Necessary	90.40 FL	*- FL
4	1		*TAILLAMP	Cracked	335.40 FL	*335.40 FL
5	1		*TAILLAMP PANEL	Repair	192.50 FL	*- FL
6	1		*REAR END PANEL	Not Necessary	482.90 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Not Necessary	174.60 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
9	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
10	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
11	1		*SET REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,466.70</b>	<b>1,166.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	207.67	113.63
<b>Total Parts (\$\$)</b>	<b>2,259.03</b>	<b>1,052.67</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,000.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	400.00
3	WIRING CHECK	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	30.00
6	TO APPLY TUFF COAT	New	150.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,450.00</b>	<b>960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >