



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002858/Kqy3m4 Date: 26/06/2023  Code: FCI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>			
Insured Veh.		Veh. Inspected	PA 9515C
Policy No.	D-220099824MBP	Coverage (\$)	0.00
Claim No.	D230000304MBP	Excess (\$)	500.00
Assign From	CAROLINE CABRERA	Assign Date	20/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA HIACE (A)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTFST22P700008481	Colour	WHITE
Odometer	70869 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	YOKOHAMA	5 mm
L/H Front Tyre	195 R15X8	YOKOHAMA	5 mm
R/H Rear Tyre	195 R15X8	YOKOHAMA	6 mm
L/H Rear Tyre	195 R15X8	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/01/2023	Inspection Date	24/03/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE MARKET VALUE IS S\$28,000.00 (EST. AVERAGE) C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	