

ASS. REC. BY:

REF:

FCZ/23002858/K943

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/IV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

201500

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PA9515C

Yr Regn:

06/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Hiace

c.c

2982

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

70869

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFTST22P 70 0008481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

19/1/23

D.O.I.

24/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/5 21h @ 1300

20/6 11h @ 2050 Car CRASH @ 10750, 33%

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S - RS. SI

Parking

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

OD

Lump Sum / I.B.X (\$

2050



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ODVehicle No. : PA9515CMake & Model : TOYOTA HIACEYear of Manufacture : 2010Chassis No. : JTFST22P700008481Engine No. : 1KD2011276

Policy No. : _____

Time of Accident : 16.55Ins Company : MS FIRSTCAPITAL

Excess : _____

Date of Accident : 19.01.2023

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items _____

Plus/Less \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items _____

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 1,600.00

Total Repair Cost _____

Contact No

Frt Counter Operation

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 -

63837362 -

The above total will be subjected to 7% G.S.T.

NOT Withheld
Resurvey By pain
11/Sept @ 2050hr

Name of Surveyor : HenrichCompany : LKKSurvey conducted on : 24/3/23 at 9.50 am**Remarks By Surveyor**(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 05 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ 500hr(e) Signature of surveyor : Pe Date: 24/3/23

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : PA9515C Case Owner : JOHARI
Make & Model : TOYOTA HIACE Year Manufacture :
Chassis No : JTFST22P700008481 Engine No : 1KD2011276
Sales Order : Supplier :
Order By : Type of Claim : OD

S/No		QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	RH SIDE PANEL CENTER	1	<i>RM</i>	\$ 1,850.00	<i>RM</i>	\$ 80.00	<i>John</i>
2	SEALANT						
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1/6/2023

10:16 AM

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: PA9515C	Case Owner	: JOHARI
Make & Model	: TOYOTA HIACE	Year of Manufacture	: 2010

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.