



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 2065X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	O/S HEADLAMP	NOT NECESSARY	860.00	-
1	O/S HEADLAMP LOWER BRACKET	NOT NECESSARY	155.00	-
1	FRONT BUMPER	WARPED/ DEFORMED	1,670.00	1,543.00
1	O/S FRONT BUMPER SIDE RETAINER	NOT NECESSARY	80.00	-
	LESS 5% DISCOUNT		-138.25	-77.15
			<b>2,626.75</b>	<b>1,465.85</b>
<b>SPECIAL NETT ITEMS</b>				
1	FRONT BUMPER CLIP (SN)	NECESSARY	40.00	40.00
1	FRONT BUMPER RIVET (SN)	NOT NECESSARY	60.00	-
			<b>100.00</b>	<b>40.00</b>
<b>LABOUR</b>				
	TO FOCUS HEADLAMP & WIRING. }		50.00	20.00
	TO RE-CODE AND PROGRAM HEADLAMP MODULE. }		280.00	-
	TO RUST PROOF PANELS.	NOT NECESSARY	150.00	-
	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME.		500.00	200.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT DAMAGE AREA.		500.00	200.00
			<b>1,480.00</b>	<b>420.00</b>
<b>GRAND TOTAL</b>			<b>4,206.75</b>	<b>1,925.85</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,500.00</b>

Report Ref No. CS/SPF23002867/Uqy3m4

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$1,800**

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**