

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004481/TPA3Q2-1
Date: 20/04/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBH6842G **Insured Vehicle No :** SLV4562K
 Date of Loss: 12/01/2021 Nature of Claim: TP Claim No: 8523971533SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH6842G**
 Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M) Engine No: YD25425426A
 Reg. Date: 23/08/2018 (Man. Year: 2017) Chassis No: JN1MC2E26Z0009009
 Colour: Silver Odometer: 0 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R16 Rear Tyre Size: 195/80 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,032.27	3,754.12	3,278.15	46.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,570.00	1,180.00	42.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,782.27	5,324.12	4,458.15	45.57
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	9,782.27	4,250.00	5,532.27	56.55
+ GST 7.00/7.00% (S\$)	684.76	297.50	387.26	56.55
Nett Amount (S\$)	10,467.03	4,547.50	5,919.53	56.55
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
Nett Liability (S\$)		4,897.50		

INSPECTION

Date of Assignment: 08/04/2021
 Date Inspected: 08/04/2021 Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ)
 56 Loyang Way #06-07, Loyang Enterprise Building
 Singapore 508775
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	667.20 FL	*667.20 FL
2	6		*REAR BUMPER SIDE CLIP LH/RH	Not Necessary	72.60 FL	*- FL
3	1		*REAR BUMPER STEP PANEL	Bent	228.30 FL	*228.30 FL
4	1		*REAR END PANEL OUTER	Repair	324.00 FL	*- FL
5	1		*TAILGATE	Bent	2,160.00 FL	*2,160.00 FL
6	1		*TAILGATE LOCK LOWER	Not Necessary	384.00 FL	*- FL
7	1		*TAILGATE LOCK UPPER	Not Necessary	178.80 FL	*- FL
8	1		*TAILGATE LOCK COVER	Deformed	84.00 FL	*84.00 FL
9	1		*TAILGATE LOCK ACTUATOR	Not Necessary	408.40 FL	*- FL
10	1		*TAILGATE STRIKER	Not Necessary	51.50 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Cut	228.00 FL	*180.80 FL
12	1		*TAILGATE CHROME GARNISH	Not Necessary	535.70 FL	*- FL
13	2		*TAILGATE STAY LH /RH	Not Necessary	431.80 FL	*- FL
14	1		*TAILGATE INNER TRIM BOARD	Not Necessary	220.00 FL	*- FL
15	1		*TAILGATE LOGO	Necessary	115.20 FL	*59.70 FL
16	1		*TAILGATE EMBLEM NV350 URBAN	Necessary	156.00 FL	*50.40 FL
17	1		*TAILGATE INNER CENTER METAL COVER	Bent	108.00 FL	*108.00 FL
18	1		*TAIL LAMP LH/RH	N/S Not Necessary / O/SCracked	576.80 FL	*288.40 FL
19	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
21	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
22	1		*REAR NO.PLATE	Not Necessary	45.00 FS	*- FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
24	1		*REAR WOODEN FLOOR BOARD	Not Necessary	250.00 FS	*- FS
25	1		*REAR PANEL CHECKER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,725.30	4,136.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	693.03	382.68
Total Parts (\$\$)	7,032.27	3,754.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD PANELS ,PANEL BEAT & ALIGN TAILGATE ,REMOVE & REPLACE DAMAGED PARTS	New	1,200.00	600.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	30.00
5	TO SPRAY PAINTING FOR REAR PORTIONS & AFFECTED AREAS	New	1,000.00	700.00
6	TO REMOVE & TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
7	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (S\$)			2,750.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >