

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 1996P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	CRACKED	1,006.25	880.00
2	FRONT BUMPER RETAINER (CONSISTENT)	CRACKED	98.00	50.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	DENTED	382.80	382.80
2	FRONT BUMPER BRACKET (CONSISTENT)	NOT NECESSARY	182.30	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	CRACKED	454.00	180.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	348.45	348.45
1	FRONT GRILLE EMBLEM -LOGO(CONSISTENT)	CRACKED	97.75	30.00
2	FRONT HEADLAMP (CONSISTENT)	SCRATCHED / CRACKED	2,296.80	2,000.00
2	FRONT HEADLAMP LOWER BRACKET (CONSISTENT)	N/S BENT	282.60	90.00
	LESS 20% DISCOUNT		-1,029.79	-792.25
			4,119.16	3,169.00
	SPECIAL NETT ITEMS			
1	FRONT BUMPER LIP (JS) (SN)(CONSISTENT)	CRACKED	1,500.00	800.00
1	FRONT GRILLE EMBLEM (TYPE R) (SN)(CONSISTENT)	NOT NECESSARY	150.00	-
2	FRONT FOG LAMP (AFTER MARKET) (SN)(CONSISTENT)	SCRATCHED	600.00	130.00
1	FRONT NUMBER PLATE (SN)(CONSISTENT)	CRACKED	60.00	60.00
			2,310.00	990.00
	<u>LABOUR</u>			
	CHECK ALL WIRING AND LIGHTING SYSTEM.		80.00	30.00
	PANEL BEATING ON AFFECTED AREAS .		800.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS .		800.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	150.00	-
			1,830.00	630.00
	GRAND TOTAL		8,259.16	4,789.00

Report Ref No. CC4/HSB23002881/Spa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,850.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/HSB23002881/Spa3q2

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor