

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI23002882/KVP3Q2**Date:** 29/03/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP004541
<b>Claimant Vehicle No :</b>	SHC5290K	<b>Insured Vehicle No :</b>	GBH7336U
Date of Loss:	22/02/2023	Nature of Claim:	TP
		Claim No:	M2301304

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC5290K</b>	Engine No:	2ZR2H37469
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU903093212
Reg. Date:	23/12/2020 (Man. Year: 2020)	Odometer:	0 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Grenlander 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Grenlander 9 mm	Rear Right Side:	Sailun 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,674.05	0.00	6,674.05	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	640.00	4,470.00	87.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,784.05</b>	<b>640.00</b>	<b>11,144.05</b>	<b>94.57</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>942.72</b>	<b>51.20</b>	<b>891.52</b>	<b>94.57</b>
<b>Nett Amount (S\$)</b>	<b>12,726.77</b>	<b>691.20</b>	<b>12,035.57</b>	<b>94.57</b>

INSPECTION

Date of Assignment:	23/03/2023		
Date Inspected:	20/03/2023	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5290K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,REAR DOOR ,RH	Serviceable	1,634.33 FL	*- FL
2	1		*PANEL SUB-ASSY ,REAR DOOR OUTSIDE HANDLE ,RH	Serviceable	243.81 FL	*- FL
3	1		*HANDLE ASSY ,REAR DOOR OUTSIDE ,RH	Serviceable	123.06 FL	*- FL
4	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM RH	Serviceable	369.60 FL	*- FL
5	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,REAR RH	Serviceable	1,161.83 FL	*- FL
6	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,RH	Serviceable	260.51 FL	*- FL
7	1		*TAPE BLACK OUT,NO.2 REAR RH	Not Necessary	44.00 FL	*- FL
8	1		*TAPE BLACK OUT,NO.3 REAR RH	Not Necessary	19.43 FL	*- FL
9	1		*TAPE BLACK OUT,NO.1 REAR RH	Not Necessary	27.62 FL	*- FL
10	1		*HINGE ASSY ,REAR DOOR ,LOWER RH	Repair	109.62 FL	*- FL
11	1		*HINGE ASSY ,REAR DOOR ,UPPER RH	Repair	124.74 FL	*- FL
12	1		*PANEL SUB-ASSY ,QUARTER ,RH	Repair	1,099.46 FL	*- FL
13	1		*LINER ,REAR WHEEL HOUSE ,RH	Serviceable	176.09 FL	*- FL
14	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Serviceable	624.54 FL	*- FL
15	1		*RIM	Serviceable	1,900.10 FL	*- FL
16	1		*DOOR STICKER TEL NO	Not Necessary	100.00 FS	*- FS
17	1		*DOOR TRIM CLIP	Not Necessary	75.00 FS	*- FS
18	1		*DOOR WEATHERSTRIP CLIP	Not Necessary	80.00 FS	*- FS
19	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
20	1		*ROCKER MOULDING CLIP	Not Necessary	65.00 FS	*- FS
21	1		*TYRE	Serviceable	350.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	8,653.74 0.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,979.69 0.00
					Total Parts (\$\$)	6,674.05 0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
4	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	200.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	440.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,110.00</b>	<b>640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >