

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|------------------------|----------------|---------|----------------------|--|
| | THE SINCERE MO | TOR REPAIRING PL | | Ref: | CS/TP23002888/Kny3m4 | |
| | 20 SHAW ROAD #0 CHING SHINE IND BUILDINGSINGAP | USTRIAL | | Date: | 28/03/2023 | |
| | ON BEHALF OF LE | EE SOON SENG | | Code: | TP280 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | | Veh. Inspected | | JRL 1281 | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | | Excess (\$) | | 0.00 | |
| | Assign From | | Assign Date | | 08/12/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | YAMAHA 115Z | c.c | | 114 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2016 | |
| | Chassis No. | PMYUE1510G0008776 | Colour | | RED | |
| | Odometer | 96504 KM | Steering | | JAMMED | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 70/80R17 | MAXXIS | | 4 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 80/90R17 | MAXXIS | | 4 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 30/11/2022 | Inspection Dat | е | 08/12/2022 | |
| | Survey held at THE SINCERE MOTOR REPAIRING PL | | | | | |
| | 20 SHAW ROAD #01-03 CHING SHINE INDUSTRIAL BUILDING SINGAPORE 367956 | | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | | 5 Worki | ng Days | |