

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CS/AIS23002898/WQY3M4**Date:** 04/07/2023**REFERENCE**

Insured/Claimant:	PANG HEE TENG	Policy No:	SP2003939118-01	
Date of Loss:	18/03/2023	Nature of Claim:	OD	Claim No: 202332006316

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ7037S	Engine No:	1NZ8192776
Make & Model:	TOYOTA AQUA HYBRID, 1.5 E S CVT (A)	Chassis No:	NHP106602876
Reg. Date:	20/07/2017 (Man. Year: 2017)	Odometer:	116502 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,205.40	2,308.90	896.50	27.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	760.00	250.00	24.75
Paintwork Labour	1,000.00	860.00	140.00	14.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,215.40	3,928.90	1,286.50	24.67
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	4,715.40	3,428.90	1,286.50	27.28
+ GST 8.00/8.00% (S\$)	377.23	274.31	102.92	27.28
Nett Amount (S\$)	5,092.63	3,703.21	1,389.42	27.28

INSPECTION

Date of Assignment:	21/03/2023	Present Location:	Kan Fook Sing Motor Workshop (Defu) Kan Fook Sing Motor Workshop (Defu) Blk 8 Defu South Street 1, Defu Industrial City #04-29 Singapore 533758
Date Inspected:	27/03/2023	Inspected At:	
Estimated Period of Repair:	6.0 days		

Adjuster: Mohdakid**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2023)
Parts:	144	TOYOTAAQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ7037S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH (WCP)	Not Necessary	190.00 F	*- F
2	10		*FRONT FENDER SHIELD CLIP (WCP)	Not Necessary	25.00 F	*- F
3	1		*FRONT DOOR RH (WCP)	Dented	680.00 F	*440.00 F
4	1		*FRONT DOOR FAME STICKER RH (WCP)	Necessary	28.00 F	*28.00 F
5	1		*FRONT DOOR OUTER MOULDING RH (WCP)	Not Necessary	120.00 F	*- F
6	1		*FRONT DOOR RUN CHANNEL RH (WCP)	Cut	70.00 F	*70.00 F
7	1		*FRONT DOOR SIDE MIRROR RH (WCP)	Missing	265.00 F	*265.00 F
8	1		*FRONT DOOR SIDE MIRROR COVER RH (WCP)	Missing	40.00 F	*40.00 F
9	1		*REAR DOOR RH (WCP)	Scratched	400.00 F	*400.00 F
10	1		*REAR DOOR FAME STICKER RH (WCP)	Necessary	25.00 F	*25.00 F
11	1		*REAR DOOR GLASS RH (WCP)	Scratched	250.00 F	*220.00 F
12	1		*REAR DOOR OUTER MOULDING RH (WCP)	Cut	35.00 F	*35.00 F
13	1		*REAR DOOR RUN CHANNEL RH (WCP)	Damaged	85.00 F	*60.00 F
14	1		*REAR FENDER RH (WCP)	Dented	480.00 F	*480.00 F
15	1		*REAR LAMP RH (WCP)	Not Necessary	185.00 F	*- F
Supplementary #1						
16	1		*REAR BUMPER SIDE RETAINER RH (WCP)	Broken	36.00 F	*36.00 F

F=Franchise part.

Sub Total (S\$)				2,914.00	2,099.00
+ Margin on L,N Items 10.00/10.00% (S\$)				291.40	209.90
Total Parts (S\$)				3,205.40	2,308.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	1,000.00	860.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO REMOVE/REFIT REAR FENDER INNER GARNISH RH	New	80.00	50.00
4	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	100.00	80.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	780.00	600.00
Gross Labour Cost (S\$)			2,010.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >