

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO		Ref:	CS3/SMR23002901/Wwy3e2		
	60 WOODLANDS I E4SINGAPORE 75		Date:	17/04/2023		
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMB 314E	Veh. Inspected	ł	FBL 7124T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	BUS/03/23/5020	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		21/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA SNIPER	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	MH3UG0740G0035379	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/90 R17	MICHELIN		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70 R17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5.	5. General Information					
	Accident Date	12/03/2023	Inspect Date /	Time	21/03/2023 (02:30 PM)	
	Survey held at	M2 GARAGE PTE LTD				
		61 WOODLANDS INDUSTRIAL PARK E9 #01-17 E9 PREMIUM SINGAPORE 757047				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMR23002901/Wwy3e2

Inspected By

Asst. Automotive Assessor

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser