



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 5023K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	633.00	633.00
2	FRONT BUMPER SIDE HOLDER @ \$22.00 (CONSISTENT)	NOT NECESSARY	44.00	-
1	FRONT BUMPER LOWER CENTRE GRILLE (CONSISTENT)	NOT NECESSARY	228.00	-
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	328.00	-
1	FRONT GRILLE RIM (CONSISTENT)	CUT	175.00	175.00
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	84.00	84.00
1	FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	3.00	3.00
	LESS 10% DISCOUNT		-149.50	-89.50
			1,345.50	805.50
	<u>LABOUR</u>			
	REMOVE REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		800.00	250.00
	RESPRAY PAINTING.		800.00	200.00
			1,600.00	450.00
	GRAND TOTAL		2,945.50	1,255.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CS/HSB23002903/Acp3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.