



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS/HSB23002903/Acp3m4 Date: 23/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8556A	Veh. Inspected	SMZ 5023K	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S3M04KOE	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	21/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KNAF3416MM5100971	Colour	BLUE	
Odometer	111825 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	MICHELIN	6 mm	
L/H Front Tyre	205/55R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2023	Inspection Date	30/03/2023	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	