



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 1008Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,655.90	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,855.95	-
1	REAR TAILLAMP	SCRATCHED	894.35	894.35
	LESS 10% DISCOUNT		-440.62	-89.44
			3,965.58	804.91
LABOUR				
	TO CHECK REAR ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.		150.00	60.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS.		800.00	400.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER.		800.00	300.00
			1,800.00	780.00
GRAND TOTAL			5,765.58	1,584.91
RECOMMENDED COST OF REPAIRS				1,584.91

Report Ref No. CS/FCI23002904/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.