

ASS. REC. BY:

REF:

AG21 23002905/kw

JL

### ASSIGNMENT

Kenneth

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Thiam 1/11  
of 0541

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMK 7124 T Yr Regn: 04, 19

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Verel c.c. 1496

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 89043 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU 3 1319114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: P. Moru 99 215 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or WIPAKA

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 9 mm R/Bal. 8 mm

L/Bal. 9 mm L/Bal. 8 mm

D.O.A. 19/3/23 D.O.I. 21/3/2023

Survey held at \_\_\_\_\_

Des. of Damages: Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 GIA & EV not ready

18/4 1 Pump & 4500k Carbur

Date/Time, File Pass to?

: Prel. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trlp: \_\_\_\_\_

Date/Time, File Return to?

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Survey Fee:

Transportation

S - RS. \$

Facilities

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |


# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721  
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

*NOT Authorized*  
*11 Days @ 4500hr*  
*Recovery After Repair*  
*5 days*

Make/Model: HONDA VEZEL  
 Engine/Chassis No.:  
 Date of accident: 19.03.23  
 Damaged area: Rear

Date: 22/03/2023  
 Claim Type: TP  
 VRN: SMK7124T



| List items |   |     |             |             |            |
|------------|---|-----|-------------|-------------|------------|
| S/N        | Parts description                                 | QTY | UNIT PRICE  | AMOUNT      |            |
| 1          | Tailgate <i>1068</i>                              | 1   | \$ 1,950.00 | \$ 1,950.00 | ✓          |
| 2          | Tailgate outer garnish                            | 1   | \$ 385.00   | \$ 385.00   | X          |
| 3          | Tailgate logo                                     | 1   | \$ 62.00    | \$ 62.00    | X          |
| 4          | Tailgate "Vezel" emblem                           | 1   | \$ 57.00    | \$ 57.00    | ✓          |
| 5          | Tailgate lamp                                     | 2   | \$ 590.00   | \$ 1,180.00 | X          |
| 6          | Tailgate buzzer                                   | 1   | \$ 269.00   | \$ 269.00   | X          |
| 7          | Tailgate inner handle                             | 1   | \$ 84.00    | \$ 84.00    | ✓          |
| 8          | Tailgate inner lock                               | 1   | \$ 285.00   | \$ 285.00   | ✓          |
| 9          | Tailgate lock sensor                              | 1   | \$ 320.00   | \$ 320.00   | X          |
| 10         | Tailgate striker                                  | 1   | \$ 85.00    | \$ 85.00    | X          |
| 11         | Tailgate trimboard                                | 1   | \$ 745.00   | \$ 745.00   | X          |
| 12         | Tailgate weatherstrip                             | 1   | \$ 185.00   | \$ 185.00   | <i>50W</i> |
| 13         | Tailgate windscreen moulding <i>112</i>           | 1   | \$ 194.00   | \$ 194.00   | ✓          |
| 14         | Taillamp <i>C 480.00</i>                          | 2   | \$ 689.00   | \$ 1,378.00 | ✓          |
| 15         | Rear bumper <i>743</i>                            | 1   | \$ 1,150.00 | \$ 1,150.00 | ✓          |
| 16         | Rear bumper retainer                              | 2   | \$ 76.00    | \$ 152.00   | X          |
| 17         | Rear bumper bracket                               | 2   | \$ 68.00    | \$ 136.00   | ^          |
| 18         | Rear bumper side cover                            | 2   | \$ 287.00   | \$ 574.00   | X          |
| 19         | Rear bumper side reflector                        | 2   | \$ 177.00   | \$ 354.00   | X          |
| 20         | Rear bumper cover retainer                        | 2   | \$ 52.00    | \$ 104.00   | X          |
| 21         | Rear bumper centre lower diffuser <i>Per 1000</i> | 1   | \$ 494.00   | \$ 494.00   | ✓          |
| 22         | Rear bumper lower cowl                            | 1   | \$ 298.00   | \$ 298.00   | X          |
| 23         | End panel <i>562</i>                              | 1   | \$ 685.00   | \$ 685.00   | ✓          |
| 24         | Tailgate "HYBRID" emblem                          | 1   | \$ 66.00    | \$ 66.00    | ✓          |
| 25         | Rear fender inner trim                            | 2   | \$ 476.00   | \$ 952.00   | X          |
| 26         | Rear licence plate lamp                           | 2   | \$ 68.00    | \$ 136.00   | X          |
| 27         | Spare tyre compartment top board                  | 1   | \$ 348.00   | \$ 348.00   | X          |
| 28         | Tools holder                                      | 1   | \$ 197.00   | \$ 197.00   | X          |
| 29         | Rear floor panel                                  | 1   | \$ 794.00   | \$ 794.00   | X          |
| 30         | Exhaust assy                                      | 1   | \$ 978.00   | \$ 978.00   | X          |
| 31         | Exhaust assy mounting                             | 2   | \$ 45.00    | \$ 90.00    | X          |
| 32         | Exhaust heat shield                               | 1   | \$ 187.00   | \$ 187.00   | ^          |
| 33         | Tailgate hinge                                    | 2   | \$ 135.00   | \$ 270.00   | X          |
| 34         | Tailgate damper                                   | 2   | \$ 177.00   | \$ 354.00   | X          |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/during/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Repair Estimate

|                      |                          |     |   |           |                     |   |
|----------------------|--------------------------|-----|---|-----------|---------------------|---|
| 35                   | End panel top garnish    | 163 | 1 | \$ 284.00 | \$ 284.00           | ✓ |
| 36                   | Rear fender arch garnish | 8   | 2 | \$ 198.00 | \$ 396.00           | X |
| <b>Subtotal</b>      |                          |     |   |           | <b>\$ 16,178.00</b> |   |
| <b>List discount</b> |                          |     |   |           | 20.00%              |   |
| <b>Total</b>         |                          |     |   |           | <b>\$ 12,942.40</b> |   |

| Special nett items |                                       |       |     |            |                    |       |
|--------------------|---------------------------------------|-------|-----|------------|--------------------|-------|
| No.                | Parts description                     |       | QTY | UNIT PRICE | AMOUNT             |       |
| 1                  | Rear bumper lower diffuser clips      | ME    | 8   | \$ 5.50    | \$ 44.00           | ✓     |
| 2                  | Rear bumper lower side cowlings clips | NN    | 12  | \$ 5.50    | \$ 66.00           | X     |
| 3                  | Tailgate outer garnish clips          | NN    | 6   | \$ 5.50    | \$ 33.00           | X     |
| 4                  | Tailgate lamp clips                   | NN    | 6   | \$ 5.50    | \$ 33.00           | X     |
| 5                  | Tailgate trimboard clips              | NN    | 10  | \$ 5.50    | \$ 55.00           | ✓     |
| 6                  | Taillamp clips                        | NN    | 6   | \$ 5.50    | \$ 33.00           | ✓     |
| 7                  | End panel top garnish clips           | NN    | 6   | \$ 5.50    | \$ 33.00           | ✓     |
| 8                  | End panel sealant                     | ME    | 1   | \$ 100.00  | \$ 100.00          | 305N  |
| 9                  | Rear licence plate & frame            | NN    | 1   | \$ 55.00   | \$ 55.00           | X     |
| 10                 | Reverse sensor                        | short | 1   | \$ 280.00  | \$ 280.00          | 2001N |
| 11                 | Reverse camera                        | NN    | 1   | \$ 450.00  | \$ 450.00          | X     |
| 12                 | Rear floor panel padding              | NN    | 1   | \$ 120.00  | \$ 120.00          | X     |
| 13                 | Rear floor panel sealant              | NN    | 1   | \$ 100.00  | \$ 100.00          | X     |
| 14                 | Tailgate windscreen inner seal        | NN    | 1   | \$ 100.00  | \$ 100.00          | 305N  |
| 15                 | Tailgate windscreen sealant           | NN    | 1   | \$ 100.00  | \$ 100.00          | 405N  |
| 16                 | Rear bumper clips                     | NN    | 10  | \$ 5.50    | \$ 55.00           | ✓     |
| 17                 | Rear fender arch garnish clips        | NN    | 12  | \$ 5.50    | \$ 66.00           | X     |
| 18                 | Sundries                              | NN    | 1   | \$ 50.00   | \$ 50.00           | X     |
| <b>Total</b>       |                                       |       |     |            | <b>\$ 1,773.00</b> |       |

| Labour                      |   |           |                     |
|-----------------------------|---|-----------|---------------------|
| No.                         | Description   | Work unit | Amount              |
| 1                           | To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.          | 7         | \$ 1,400.00         |
| 2                           | To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings. | 0.25      | \$ 50.00            |
| 3                           | To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.                       | 0.5       | \$ 100.00           |
| 4                           | To remove and refit, straighten and readjust exhaust pipe and replace exhaust silencer.   | 0.5       | \$ NN 100.00        |
| 5                           | To remove and refit rear windscreen to facilitate repair work.  | 0.75      | \$ 150.00           |
| 6                           | To rust proof all affected portions after repair.   | 0.5       | \$ 100.00           |
| 7                           | Supply spray paint material and necessary items to respray affected area / panel.   | 6         | \$ 1,200.00         |
| <b>Total labour</b>         |   |           | <b>\$ 3,100.00</b>  |
| <b>Estimate Grand Total</b> |   |           | <b>\$ 17,815.40</b> |

✓  
 X  
 X  
 X  
 ✓  
 ✓  
 305N  
 X  
 2001N  
 X  
 X  
 305N  
 405N  
 ✓  
 X  
 X

600  
 200  
 600  
 X  
 1200  
 600  
 700