

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III23002912/KVY3E2**Date:** 05/06/2023REFERENCE

Insured/Claimant: KINETIC LOCOMOTIVE PTE LTD

Policy No: D22MFL0008937

Date of Loss: 18/03/2023

Nature of Claim: OD

Claim No: MFL2023D0003442

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLU3550G**

Make & Model: HONDA SHUTTLE, 1.5 (A)

Engine No: LEB6326749

Reg. Date: 29/11/2017 (Man. Year: 2017)

Chassis No: GP71121680

Colour: Metallic Black

Odometer: 190204 km

Engine Capacity: 1496 cc

Market Value/New Car Price: S\$75,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: 'GREENTRAC' 8 mm

Rear Left Side: Firenza 5 mm

Front Right Side: 'GREENTRAC' 8 mm

Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		5,450.00		
- Excess (S\$)	1,450.00	1,450.00	0.00	0.00
(S\$)	-1,450.00	4,000.00	-5,450.00	375.86
+ GST 8.00/8.00% (S\$)	0.00	320.00	-320.00	
Nett Amount (S\$)	-1,450.00	4,320.00	-5,770.00	397.93

INSPECTION

Date of Assignment: 21/03/2023

Date Inspected: 24/03/2023 Inspected At:

Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jun 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU3550G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >