

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG123002915/UVY3E2**Date:** 30/03/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SJJ3869U**Insured Vehicle No :** GBC875C

Date of Loss: 17/03/2023

Nature of Claim: TP

Claim No: CDMCG23000670

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJJ3869U**

Make &amp; Model: NISSAN SYLPHY, 1.5 4AT (A)

Engine No: HR15374181A

Reg. Date: 10/09/2008 (Man. Year: 2008)

Chassis No: JN1BAAG11Z0106620

Colour: Gold

Odometer: 244995 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Triangle 6 mm

Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm

Rear Right Side: Triangle 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,878.80	2,963.39	8,915.41	75.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,360.00	930.00	40.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,168.80</b>	<b>4,323.39</b>	<b>9,845.41</b>	<b>69.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,168.80</b>	<b>3,200.00</b>	<b>10,968.80</b>	<b>77.42</b>

INSPECTION

Date of Assignment: 21/03/2023

Date Inspected: 21/03/2023 Inspected At:

2ND Auto Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre  
Singapore 417808

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
<b>Parts:</b>	143	NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJJ3869U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,286.00 FL	*- FL
2	1		*FRONT BUMPER	Distorted	1,125.00 FL	*577.90 FL
3	1		*FRONT BUMPER LOWER SKIRTING (BODY KIT)	Torn	980.00 FL	*600.00 FL
4	1		*LHS FRONT FENDER	Badly Dented	782.00 FL	*481.00 FL
5	1		*BONNET CHROME MOULDING	Not Necessary	192.00 FN	*- FN
6	1		*BONNET INNER LOCK	Not Necessary	298.00 FN	*- FN
7	1		*FRONT BRACE PANEL	Not Necessary	112.00 FN	*- FN
8	1		*FRONT CENTRE CHROME GRILLE	Not Necessary	624.00 FN	*- FN
9	1		*FRONT CENTRE CHROME GRILLE BADGE	Not Necessary	98.00 FN	*- FN
10	1		*LHS FRONT FENDER INNER SHIELD	Torn	328.00 FN	*122.30 FN
11	1		*LHS FRONT FENDER SIGNAL LAMP (NPA)	Not Necessary	0.00 FN	*- FN
12	1		*LHS FRONT FENDER INNER SIDE PANEL	Repair	298.00 FN	*- FN
13	2		*FRONT BUMPER SIDE RETAINERS	Cracked / Necessary	224.00 FN	*70.00 FN
14	1		*FRONT BUMPER REINFORCEMENT	Twisted	598.00 FN	*561.90 FN
15	1		*FRONT BUMPER REINFORCEMENT FOAM	Torn	148.00 FN	*148.00 FN
16	2		*FRONT BUMPER FOG LAMP RHS & LHS	Not Necessary	784.00 FN	*- FN
17	2		*FRONT BUMPER FOG LAMP COVER RHS & LHS	Not Necessary	244.00 FN	*- FN
18	1		*FRONT BUMPER TOW COVER	Not Necessary	48.00 FN	*- FN
19	2		*FRONT BUMPER RH & LH SIDE CHROME MOULDING	Necessary	124.00 FN	*124.00 FN
20	1		*FRONT BUMPER LOWER COVER	Not Necessary	572.00 FN	*- FN
21	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	278.00 FN	*- FN
22	1		*RHS & LHS HEADLAMP	N/S Cracked / O/S NotNecessary	1,973.00 FN	*476.20 FN
23	1		*LHS FRONT SHOCK ABSORBER	Not Necessary	582.00 FN	*- FN
24	1		*LHS FRONT LOWER ARM	Not Necessary	482.00 FN	*- FN
25	1		*LHS FRONT KNUCKLE ARM	Not Necessary	398.00 FN	*- FN
26	1		*LHS FRONT WHEEL BEARING	Not Necessary	298.00 FN	*- FN
27	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*30.00 FS
28	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*FRONT NUMBER PLATE W/HOLDER	Bent	75.00 FS	*40.00 FS
30	1		*FRONT BUMPER LOWER COVER CLIPS	Not Necessary	60.00 FS	*- FS
31	1		*LHS FRONT FENDER SHIELD CLIPS	Repeated	80.00 FS	*- FS
32	1		*LHS FRONT SPORTS RIM	Warped	780.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>14,001.00</b>	<b>3,611.30</b>
- List Item Discount on L Items 30.00/30.00% (S\$)	1,251.90	497.67
- Nett Item Discount on N Items 10.00/10.00% (S\$)	870.30	150.24

**Total Parts (S\$) 11,878.80 2,963.39**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; AND REPLACE DAMAGED PARTS	New	1,000.00	450.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	900.00	800.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION (INCLUDING FOCUS OF HEADLAMP BEAM)	New	150.00	20.00
4	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	60.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,290.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >