

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS23002918/KYA3Q2**Date:** 07/07/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2005022599
<b>Claimant Vehicle No :</b>	SLU3098X	<b>Insured Vehicle No :</b>	SMG2515C
Date of Loss:	16/03/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLU3098X</b>	Engine No:	LEB5577832
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71048294
Reg. Date:	28/11/2017 (Man. Year: 2017)	Odometer:	424709 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Grand Trac 9 mm	Rear Left Side:	Roadstone 7 mm
Front Right Side:	Grand Trac 9 mm	Rear Right Side:	Roadstone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,728.08	936.08	1,792.00	65.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,470.00	1,250.00	45.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,448.08</b>	<b>2,406.08</b>	<b>3,042.00</b>	<b>55.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
<b>(S\$)</b>	5,448.08	1,900.00	3,548.08	65.13
<b>+ GST 8.00/8.00% (S\$)</b>	435.85	152.00	283.85	65.13
<b>Nett Amount (S\$)</b>	<b>5,883.93</b>	<b>2,052.00</b>	<b>3,831.93</b>	<b>65.13</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		26.75		
<b>Nett Liability (S\$)</b>		<b>2,318.75</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,300.00</b>		

INSPECTION

Date of Assignment:	21/03/2023	Optima Werkz Pte Ltd (HQ)
Date Inspected:	23/03/2023 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2023)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU3098X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent / Warped	972.20 FL	*972.20 FL
2	1		*REAR DOOR PROTECTIVE STICKER LH	Not Necessary	45.30 FL	*- FL
3	1		*REAR DOOR RUBBER SEAL LH	Serviceable	88.50 FL	*- FL
4	1		*REAR FENDER LH	Repair	969.70 FL	*- FL
5	1		*REAR RIM COVER LH	Dented	197.90 FL	*197.90 FL
6	1		*REAR BUMPER	Repair	876.70 FL	*- FL
7	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	34.80 FL	*- FL
8	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR DOOR INNER TRIM BOARD CLIPS LH	Not Necessary	50.00 FS	*- FS
10	1		*REAR FENDER QUARTER GLASS SEALANT LH	Not Necessary	80.00 FS	*- FS
11	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	3,365.10 1,170.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	637.02 234.02
					Total Parts (\$\$)	2,728.08 936.08

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS & ETC	New	1,000.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH ,REAR DOOR LH ,REAR FENDER LH ,REAR BUMPER & ETC	New	1,000.00	800.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF REAR DOOR LH	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER QUARTER GLASS LH ,REAR FENDER QUARTER GLASS SEALANT & ETC	New	150.00	0.00
5	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH ,UPHOLSTERY CUSHION SET & ETC .TO EFFECT REPLACE OF REAR FENDER LH	New	250.00	60.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,720.00</b>	<b>1,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >