

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG23002919/SQY3E2**Date:** 19/07/2023REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1800062076   |
| <b>Claimant Vehicle No :</b> | SMK5277Z                             | <b>Insured Vehicle No :</b> | SCV6318T     |
| Date of Loss:                | 21/03/2023                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1031370512SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |             |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No:                     | <b>SMK5277Z</b>                   |             |             |
| Make & Model:               | HONDA SHUTTLE, 1.5 G CVT (A)      | Engine No:  | L15B6002359 |
| Reg. Date:                  | 12/04/2019 (Man. Year: 2019)      | Chassis No: | GK82001987  |
| Colour:                     | White                             | Odometer:   | 60676 km    |
| Engine Capacity:            | 1496 cc                           |             |             |
| Market Value/New Car Price: | N/A                               |             |             |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |             |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 185/60 R15    | Rear Tyre Size:  | 185/60 R15    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 12,665.19         | 6,106.87          | 6,558.32          | 51.78         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,060.00          | 2,390.00          | 2,670.00          | 52.77         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>17,725.19</b>  | <b>8,496.87</b>   | <b>9,228.32</b>   | <b>52.06</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>6,800.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>17,725.19</b>  | <b>6,800.00</b>   | <b>10,925.19</b>  | <b>61.64</b>  |

INSPECTION

|                             |            |  |
|-----------------------------|------------|--|
| Date of Assignment:         | 21/03/2023 |  |
| Date Inspected:             | 22/03/2023 | Inspected At: CAR HUB HOLDINGS PTE LTD - AMK (HQ)<br>5035 Ang Mo Kio Ind Park 2, #01-355<br>Singapore 569538 |
| Estimated Period of Repair: | 8.0 days   |  |

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars  | Condition     | Repairer's | Amount       |
|-----|-----|----------|--|---------------|------------|--------------|
| 1   | 1   |          | <b>*TAILGATE</b>                                       | Dented        | 1,295.00 F | *1,295.00 FL |
| 2   | 1   |          | <b>*TAILGATE LOGO</b>                                  | Not Necessary | 98.30 F    | *- FL        |
| 3   | 1   |          | <b>*TAILGATE EMBLEM SHUTTLE</b>                        | Necessary     | 95.00 F    | *95.00 FL    |
| 4   | 1   |          | <b>*TAILGATE WINDSCREEN MOULDING</b>                   | Necessary     | 168.65 F   | *168.65 FL   |
| 5   | 1   |          | <b>*TAILGATE WEATHERSTRIP</b>                          | Cut           | 217.59 F   | *217.59 FL   |
| 6   | 1   |          | <b>*TAILGATE OUTER GARNISH</b>                         | Not Necessary | 256.60 F   | *- FL        |
| 7   | 1   |          | <b>*TAILGATE OUTER CHROME MOULDING GARNISH</b>         | Not Necessary | 268.00 F   | *- FL        |
| 8   | 1   |          | <b>*TAILGATE INNER LOCK</b>                            | Not Necessary | 294.35 F   | *- FL        |
| 9   | 2   |          | <b>*TAILGATE NUMBER PLATE LAMP</b>                     | Not Necessary | 178.80 F   | *- FL        |
| 10  | 2   |          | <b>*TAILGATE STOPPER RUBBER</b>                        | Not Necessary | 126.00 F   | *- FL        |
| 11  | 1   |          | <b>*TAILLAMP ASSY N/S</b>                              | Cracked       | 697.00 F   | *697.00 FL   |
| 12  | 1   |          | <b>*REAR BUMPER</b>                                    | Cut           | 856.40 F   | *856.40 FL   |
| 13  | 2   |          | <b>*REAR BUMPER SIDE RETAINER</b>                      | Necessary     | 240.40 F   | *240.40 FL   |
| 14  | 2   |          | <b>*REAR BUMPER BRACKET</b>                            | Not Necessary | 136.40 F   | *- FL        |
| 15  | 1   |          | <b>*REAR BUMPER SPONGE N/S</b>                         | Torn          | 198.00 F   | *47.00 FL    |
| 16  | 1   |          | <b>*REAR BUMPER TOW COVER</b>                          | Not Necessary | 48.00 F    | *- FL        |
| 17  | 1   |          | <b>*REAR BUMPER REFLECTOR N/S</b>                      | Cracked       | 115.00 F   | *64.00 FL    |
| 18  | 1   |          | <b>*REAR BUMPER REFLECTOR GARNISH N/S</b>              | Cut           | 164.70 F   | *58.00 FL    |
| 19  | 1   |          | <b>*REAR BUMPER LOWER COVER N/S</b>                    | Damaged       | 211.40 F   | *112.00 FL   |
| 20  | 1   |          | <b>*REAR END PANEL</b>                                 | Dented        | 765.50 F   | *567.00 FL   |
| 21  | 1   |          | <b>*REAR END PANEL TOP GARNISH</b>                     | Not Necessary | 428.30 F   | *- FL        |
| 22  | 1   |          | <b>*ANTENNA AMPLIFIER MODULE</b>                       | Not Necessary | 197.30 F   | *- FL        |
| 23  | 1   |          | <b>*SMART BUZZER</b>                                   | Damaged       | 146.20 F   | *146.20 FL   |
| 24  | 1   |          | <b>*REAR FENDER N/S</b>                                | Dented        | 960.90 F   | *960.90 FL   |
| 25  | 1   |          | <b>*REAR FENDER AIR VENT N/S</b>                       | Damaged       | 112.00 F   | *112.00 FL   |
| 26  | 1   |          | <b>*REAR FENDER QUARTER GLASS MOULDING N/S</b>         | Necessary     | 145.00 F   | *145.00 FL   |
| 27  | 1   |          | <b>*REAR FENDER INNER GARNISH LOWER N/S</b>            | Cracked       | 563.20 F   | *563.20 FL   |
| 28  | 1   |          | <b>*REAR FENDER INNER SHIELD N/S</b>                   | Distorted     | 194.60 F   | *194.60 FL   |
| 29  | 1   |          | <b>*SPARE TYRE FLOOR EXTENSION N/S</b>                 | Bent          | 497.60 F   | *214.00 FL   |
| 30  | 1   |          | <b>*REAR TOOLS TRAY N/S</b>                            | Deformed      | 273.40 F   | *273.40 FL   |
| 31  | 1   |          | <b>*REAR WHEEL HOUSE INNER PANEL LOWER N/S</b>         | Not Necessary | 980.60 F   | *- FL        |
| 32  | 1   |          | <b>*SUNDRIES</b>                                       | Necessary     | 50.00 FS   | *30.00 FS    |
| 33  | 1   |          | <b>*TAILGATE SEALANT</b>                               | Necessary     | 100.00 FS  | *40.00 FS    |
| 34  | 1   |          | <b>*SET TAILGATE OUTER GARNISH CLIPS</b>               | Not Necessary | 45.00 FS   | *- FS        |
| 35  | 1   |          | <b>*SET TAILGATE TRIMBOARD CLIPS</b>                   | Not Necessary | 60.00 FS   | *- FS        |
| 36  | 2   |          | <b>*TAILGATE LAMP SEAL</b>                             | Not Necessary | 60.00 FS   | *- FS        |
| 37  | 2   |          | <b>*SET TAILGATE LAMP CLIPS</b>                        | Not Necessary | 60.00 FS   | *- FS        |
| 38  | 1   |          | <b>*SET TAILGATE WINDSCREEN PRIMER &amp; CLEANER</b>   | Necessary     | 100.00 FS  | *20.00 FS    |
| 39  | 1   |          | <b>*SET TAILGATE WINDSCREEN SEALANT</b>                | Repeated      | 80.00 FS   | *- FS        |
| 40  | 1   |          | <b>*TAILGATE WINDSCREEN INNER SEAL</b>                 | Necessary     | 60.00 FS   | *30.00 FS    |
| 41  | 1   |          | <b>*SET REAR BUMPER CLIPS</b>                          | Necessary     | 80.00 FS   | *30.00 FS    |
| 42  | 1   |          | <b>*REAR END PANEL SEALANT</b>                         | Necessary     | 100.00 FS  | *30.00 FS    |
| 43  | 1   |          | <b>*SET REAR END PANEL TOP GARNISH CLIPS</b>           | Not Necessary | 45.00 FS   | *- FS        |
| 44  | 1   |          | <b>*SET REAR FENDER GLASS PRIMER &amp; CLEANER N/S</b> | Necessary     | 100.00 FS  | *20.00 FS    |
| 45  | 1   |          | <b>*REAR FENDER GLASS SEALANT N/S</b>                  | Necessary     | 80.00 FS   | *30.00 FS    |
| 46  | 1   |          | <b>*REAR FENDER GLASS INNER SEAL N/S</b>               | Necessary     | 60.00 FS   | *20.00 FS    |
| 47  | 1   |          | <b>*SET REAR FENDER INNER GARNISH LOWER CLIPS N/S</b>  | Necessary     | 45.00 FS   | *20.00 FS    |
| 48  | 1   |          | <b>*SET REAR FENDER INNER SHIELD CLIPS N/S</b>         | Necessary     | 30.00 FS   | *15.00 FS    |
| 49  | 1   |          | <b>*REAR TYRE N/S</b>                                  | Not Necessary | 280.00 FS  | *- FS        |
| 50  | 1   |          | <b>*SET REVERSE SENSOR C/W MODULE</b>                  | Shorted       | 300.00 FS  | *200.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition   | Repairer's | Amount   |
|-----|-----|----------|-------------|---|------------|----------|
|     |     |          |             | Sub Total (S\$)                                   | 12,665.19  | 7,512.34 |
|     |     |          |             | - List Item Discount on L Items 0.00/20.00% (S\$) | 0.00       | 1,405.47 |
|     |     |          |             | Total Parts (S\$)                                 | 12,665.19  | 6,106.87 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS  | New      | 1,800.00        | 1,200.00        |
| 2                               | TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTING  | New      | 100.00          | 30.00           |
| 3                               | TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR  | New      | 200.00          | 80.00           |
| 4                               | TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE   | New      | 100.00          | 20.00           |
| 5                               | TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE THE REPAIR  | New      | 180.00          | 120.00          |
| 6                               | TO REMOVE AND REFIT N/S REAR FENDER GLASS TO FACILITATE THE REPAIR  | New      | 150.00          | 80.00           |
| 7                               | TO REMOVE AND REFIT N/S REAR TYRE TO REPLACE N/S REAR TYRE. TO PERFORM TYRE BALANCING   | New      | 100.00          | 0.00            |
| 8                               | TO ALIGN ON REAR CHASSIS FRAME AND TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER  | New      | 350.00          | 0.00            |
| 9                               | TO MEASURE, DRILL HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS  | New      | 80.00           | 30.00           |
| 10                              | TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION   | New      | 200.00          | 30.00           |
| 11                              | SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE, REAR BUMPER, REAR END PANEL, N/S REAR FENDER, REAR WHEEL HOUSING PANEL, SPARE TYRE EXTENSION PANEL AND OTHER AFFECTED AREA / PANEL | New      | 1,800.00        | 800.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>5,060.00</b> | <b>2,390.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >