

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23002922/KYA3Q2**Date:** 31/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220109843
<b>Claimant Vehicle No :</b>	SNG8358M	<b>Insured Vehicle No :</b>	SMG1268Y
Date of Loss:	16/03/2023	Nature of Claim:	TP
		Claim No:	2512956311SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNG8358M</b>	Engine No:	2ZR2N33052
Make & Model:	TOYOTA PRIUS, 1.8 PLUS (A)	Chassis No:	JTDZS3EU60J068280
Reg. Date:	07/09/2022 (Man. Year: 2021)	Odometer:	42156 km
Colour:	Metallic Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,002.75	3,440.25	562.50	14.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	850.00	650.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,502.75</b>	<b>4,290.25</b>	<b>1,212.50</b>	<b>22.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>(S\$)</b>	5,502.75	3,400.00	2,102.75	38.21
<b>+ GST 8.00/8.00% (S\$)</b>	440.22	272.00	168.22	38.21
<b>Nett Amount (S\$)</b>	<b>5,942.97</b>	<b>3,672.00</b>	<b>2,270.97</b>	<b>38.21</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,074.00</b>		

**INSPECTION**

Date of Assignment:	21/03/2023	Optima Werkz Pte Ltd (HQ)
Date Inspected:	21/03/2023 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Buckled	556.00 FL	*556.00 FL
2	1		*FRONT BUMPER EXTENSION LH	Repair	88.00 FL	*- FL
3	1		*AIR INTAKE DUCT LH	Mtg Cracked	135.00 FL	*135.00 FL
4	1		*FRONT BUMPER SIDE SUPPORT LH	Distorted	92.00 FL	*92.00 FL
5	1		*DAYTIME RUNNING LAMP ASSY LH	Mtg Cracked	585.00 FL	*585.00 FL
6	1		*FRONT FENDER SUB-ASSY LH	Bent	998.00 FL	*521.00 FL
7	1		*FRONT FENDER PROTECTOR UPPER LH	Serviceable	55.00 FL	*- FL
8	2		*FRONT FENDER SEAL LH	Serviceable	14.00 FL	*- FL
9	1		*FRONT FENDER TO COWL SIDE SEAL LH	Serviceable	66.00 FL	*- FL
10	1		*FRONT FENDER LINER LH	Distorted	222.00 FL	*172.00 FL
11	1		*HEADLAMP UNIT ASSY LH	Cut	2,526.00 FL	*2,526.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	5,337.004,587.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,334.251,146.75
					Total Parts (\$\$)	4,002.753,440.25

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE ,REPLACE /REPAIR ,REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED DAMAGED PARTS	New	600.00	400.00
2	LABOUR TO CHECK ,RECTIFY REMOVE & REPLACE /REFIX FRONT DAYTIME RUNNING LIGHT & HEADLAMP ASSY .TO ALIGN HEADLAMP ALIGNMENT & CHECK ALL LIGHTING WIRING IN PROPER WORKING	New	180.00	20.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
4	LABOUR TO PUTTY ,RESPRAY AND POLISH FRONT BUMPER ,FRONT LH FENDER AND OTHERS ACCIDENT AFFECTED AREAS	New	600.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,500.00</b>	<b>850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >