

(06/11/19)

REF:

NS/INC23002960/Svp3

ASS. REC. BY:

EST

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLU 636M Inc

Policy No. _____

Claims No. MT/1216684-001


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: 2 days Res: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: Shc3438RYr Regn: 7/11/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make: Hyundaicc 1880Colour Blue

A/C: Insured / Std / NI / NA

Sp. Reading 278846

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1cmh8516VLU188114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim, or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / WIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wals + Lancer

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 17/2/23D.O.L. 22/2/23 330pSurvey held at Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L/S = 800

22/3/23 Ifran confirmed final fig \$600 (red 605.24, 50%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 5/4/23-typist

Report Format: TP

Lump Sum / I.B.I: (\$ 600)

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation

S + RS: \$ _____

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 1 Singapore 408649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 22.02.2023 13:33

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5886816

JC NO305546473


COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P) UNIT CARD NO.	REGN NO: SHC3438R	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 22.02.2023 11:30
	YR OF MANU. 07.11.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLU188114	COMPLETION DATE/TIME:

JOB DESCRIPTION

cident Date: 17.02.2023
TURE: 3P 17.02.2023

NO 0010 LABOR CODE PB

DESCRIPTION
LUMPSUM REPAIR-SHC3438R-TP



RED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to.: SHC3438R LIMITS

Vehicle No.: SHC3438R

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard