



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002961/Uvy3e2 Date: 14/04/2023 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBH 2521J	Veh. Inspected	SMW 7900G
Policy No.	D-23100449MFCV/67	Coverage (\$)	0.00
Claim No.	D23000979MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	22/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1332
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	W1K1183842N106244	Colour	GREY
Odometer	29380 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/40Z R18	PIRELLI	8 mm
L/H Front Tyre	245/40Z R18	PIRELLI	8 mm
R/H Rear Tyre	245/40Z R18	PIRELLI	8 mm
L/H Rear Tyre	245/40Z R18	PIRELLI	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	18/03/2023	Inspection Date	22/03/2023
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	