

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIS 23002967/UP93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: GBK 7197M

at Workshop m/s 2nd Auto.

of _____

Insured: GSH 7542R

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 880k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: 21 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3 676A

Vehicle: IN / OUT

Date: _____

Person Contacted: HIA 25734

Veh No: GBK 7197M

Yr Regn: 05/11/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Toyota Proace DXGL c.c 2754

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 74588

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GDM 2012009534

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 195-1215

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

grenlander

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 03/03/23

D.O.I. 22/03/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Int.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

207 \$ 11k.

27/3/23 4/5 @ 2300 in hand AM / ony

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

VEHICLE NO. GBK 7197M TOYOTA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT	
	PARTS (LIST ITEMS)					
1	Front bumper	Del/torn		1752.00	/	687
2	Front bumper side brackets @98.20	N/s n/s o/s cae		196.40	120	
1	Front bumper lower grille	REFIX 11		0.00	X	
1	RHS Headlamp	Scn		1420.00	/	861.20
1	RHS Headlamp inner bracket	NS		112.00	X	
1	RHS Side lamp (signal)	NS		872.00	X	
1	RHS Side lamp (signal) brackets	NS		112.00	X	
1	RHS Fog lamp	Scn		652.00	X	
1	RHS Fog lamp cover	gross/torn		124.00	/	
1	RHS side view mirror assembly	Scn		798.00	/	688.50
1	RHS Front corner panel	R		672.00	X	
1	RHS Front door	R		1248.00	X	
1	RHS Front door inner trim	REFIX 11		0.00	X	
1	RHS Front door moulding	11		172.00	X	
1	RHS Front door glass run channel	11		112.00	X	
1	RHS Front door hinges @49.00	11		98.00	X	
1	RHS Front door lower step garnish	gross		124.00	/	
1	RHS Front door outer handle	REFIX 11		0.00	X	
				8464.40		
		less	25%	2116.10	25%	
				6348.30		
	SPECIAL NETT ITEMS					
1	RHS Front door inner trim clips	11		80.00	X	
1	RHS Front door company address sticker	11		120.00	40	
1	Front number plate	REFIX 11		0.00	X	
	Total Parts			6548.30		

not authorized
 22/3/23
 4/54 2300
 3 days
 the place after repair

VEHICLE NO. GBK 7197M TOYOTA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts & components	1000.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	500
3	To check electrical wiring at damage areas & focus headlamp beam	150.00	20
4	To conduct computerised wheel alignment test	120.00	11X
5	To perform anti rust treatment on affected areas	150.00	11X
	Labour Total :	2420.00	
	TOTAL (PARTS & LABOUR):	8968.00	

PRELIMINARY ESTIMATE

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-25789
252
193267
40