

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 6040T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,032.30	-
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	61.70	61.70
1	REAR TAILGATE "FREED" EMBLEM	NECESSARY	48.60	48.60
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	56.20	-
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-239.76	-22.06
			959.04	88.24
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	40.00	-
			120.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST REAR ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR BUMPER.		500.00	300.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER & ETC.		500.00	400.00
	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	NOT NECESSARY	150.00	-
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANSIM & ETC. BACK TO ORIGINAL OPERATIONS.	NOT NECESSARY	120.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM.		80.00	15.00
			1,350.00	715.00
	GRAND TOTAL		2,429.04	803.24

Report Ref No. CS/AGI23002971/Kvy3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 803.24

Report Ref No. CS/AGI23002971/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser