



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9699U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------------------------------------------------------|--------------------------------------|-------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT BUMPER | DENTED/CUT | 300.00 | 300.00 |
| 15 | FRONT BUMPER CLIPS | NECESSARY | 30.00 | 30.00 |
| 1 | HEADLAMP RH | MTG CRACKED | 230.00 | 230.00 |
| 1 | HEADLAMP RH LOWER GARNISH | SERVICEABLE | 120.00 | - |
| 1 | FRONT FENDER RH | BENT | 260.00 | 260.00 |
| 1 | FRONT FENDER COWLING RH | CRACKED | 85.00 | 85.00 |
| 10 | FRONT FENDER COWLING CLIP | NECESSARY | 20.00 | 20.00 |
| 1 | SIDE MIRROR ASSY RH | CRACKED | 260.00 | 260.00 |
| 1 | FRONT DRIVER DOOR RH | WARPED | 700.00 | 700.00 |
| 1 | FRONT SHOCK ABSORBER RH | BENT | 120.00 | 120.00 |
| 1 | FRONT SHOCK ABSORBER TOP MOUNTING RH | BENT | 50.00 | 50.00 |
| 1 | KNUCKLE ARM RH | BENT | 165.00 | 165.00 |
| 1 | FRONT WHEEL BEARING RH WITH HUB | NECESSARY | 120.00 | 120.00 |
| 1 | FRONT LOWER ARM RH | BENT | 120.00 | 120.00 |
| 1 | STEERING TIE ROD LH OUTER | SNAPPED | 28.00 | 28.00 |
| 1 | STEERING TIE ROD END RH INNER | SNAPPED | 35.00 | 35.00 |
| 1 | STABILISER LINK RH | SNAPPED | 35.00 | 35.00 |
| 1 | FRONT RH RIM | BENT | 170.00 | 170.00 |
| 1 | ENGINE CROSSMEMBER | BENT | 350.00 | 350.00 |
| | | | 3,198.00 | 3,078.00 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | TYRE - 185/70 R14 (80%) (SN) | MISSING | 140.00 | 112.00 |
| | | | 140.00 | 112.00 |
| <u>LABOUR</u> | | | | |
| TO CHECK WIRING AND REFOCUS HEADLAMP. | | | 20.00 | 20.00 |
| TO CHECK AND RE-ADJUST WHEEL ALIGNMENT. | | | 80.00 | 60.00 |
| TO DISMANTLE & TRANSFER FRONT DRIVER DOOR INNER PARTS, TRIMBOARD & WIRING HARNESS. | | | 90.00 | 60.00 |
| TOTO DISMANTLE & REPLACE FRONT CROSSMEMBER & RH SUSPENSION. | | | 380.00 | 280.00 |

Report Ref No. CS/SMO23002973/Kvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|---------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| | TO DISMANTLE & REPLACE DAMAGED PARTS. TO REFIT & ALIGN FRONT FENDER RH. TO KNOCK & REPAIR THE AFFECTED AREAS. | | 800.00 | 500.00 |
| | TO SPRAY FRONT FENDER RH, FRONT DOOR RH INNER & OUTER. | | 650.00 | 480.00 |
| | | | 2,020.00 | 1,400.00 |
| GRAND TOTAL | | | 5,358.00 | 4,590.00 |

| | | | | |
|-----------------------------------------------------------------------------|--|--|--|------------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 3,650.00 |
| LESS EXCESS | | | | -2,500.00 |
| NETT LIABILITY | | | | 1,150.00 |

Report Ref No. CS/SMO23002973/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.