

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002974/KVP3Q2
Date: 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00182152204	
Claimant Vehicle No :	SJQ4629C	Insured Vehicle No :	SMD6669G	
Date of Loss:	20/03/2023	Nature of Claim:	TP	Claim No: SNM23D202133/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ4629C		Engine No:	G4FC9U653005
Make & Model:	HYUNDAI HD AVANTE, 1.6 (A)		Chassis No:	KMHDU41BR9U757836
Reg. Date:	13/05/2009 (Man. Year: 2009)		Odometer:	207679 km
Colour:	White			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,024.76	3,069.77	1,954.99	38.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	895.00	485.00	35.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,404.76	3,964.77	2,439.99	38.10
Approved Total (Overridden) (S\$)		3,150.00		
Nett Amount (S\$)	6,404.76	3,150.00	3,254.76	50.82

INSPECTION

Date of Assignment:	22/03/2023	
Date Inspected:	27/03/2023	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts: 143	HYUNDAI HD AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJQ4629C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,188.40 FL	*985.90 FL
2	2		*REAR BOOT LID HINGES L/R	Repair	225.40 FL	*- FL
3	1		*REAR BOOT LID LOGO	Necessary	32.90 FL	*32.90 FL
4	2		*REAR LAMP L/R	Serviceable	652.40 FL	*- FL
5	1		*REAR BUMPER	Cracked	582.20 FL	*582.20 FL
6	2		*REAR BUMPER SIDE RETAINER L/R	Serviceable	84.60 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Cracked	286.20 FL	*286.20 FL
8	4		*REAR BUMPER REINFORCEMENT BRACKET L/R	Repair	101.20 FL	*- FL
9	2		*REAR BUMPER BRACKET L/R	Cracked	156.60 FL	*156.60 FL
10	1		*REAR BUMPER INNER SPONGE	Cracked	485.10 FL	*108.20 FL
11	1		*REAR END PANEL	Bent	485.10 FL	*485.10 FL
12	1		*REAR END PANEL TOP GARNISH	Dented	89.30 FL	*89.30 FL
13	1		*REAR BOOT WEATHERSTRIP (50%)	Distorted / Dented	94.80 FS	*59.25 FS
14	1		*REAR EXHAUST PIPE	Repair	693.80 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
16	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
17	1		*REAR BUMPER SPOILER	Dented / Buckled	450.00 FS	*450.00 FS
18	1		*REAR BOOT MECHANISM LOCK	Dented	168.00 FL	*168.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,071.00	3,648.65
- List Item Discount on L Items 20.00/20.00% (\$)	1,046.24	578.88
Total Parts (\$)	5,024.76	3,069.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS	New	80.00	15.00
2	TO REMOVE ,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT	New	400.00	400.00
3	TO REMOVE ,REPLACE EXHAUST SILENCER	New	150.00	0.00
4	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	400.00	400.00
5	TO REMOVE & RENEW REVERSE SENSOR	New	250.00	50.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	30.00
Gross Labour Cost (S\$)			1,380.00	895.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >