



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA23002980/Awy3m4 Date: 27/04/2023  Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YM 5342R	Veh. Inspected	SKA 6033E	
Policy No.	BVFCB0013662203	Coverage (\$)	0.00	
Claim No.	NSV2300074/SG	Excess (\$)	0.00	
Assign From	GOH STELLA	Assign Date	22/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JTDGG20W305001785	Colour	GREY	
Odometer	112755 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65R15	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/03/2023	Inspection Date	22/03/2023	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		