



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 5235B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT LH MIRROR ARM	BENT / CRACKED	1,470.00	1,299.00
1	FRONT LH MIRROR ARM MOTOR	DAMAGED / JAMMED	1,640.00	1,366.96
1	FRONT LH "ELECTRONICS" SIDE MIRROR	BROKEN	1,015.00	650.00
2	FRONT LH MIRROR ARM COVER @\$430.00	NO SUCH PARTS	860.00	-
1	FRONT LH CORNER PANEL	CRACKED	745.20	745.20
1	FRONT LH CORNER TOP COVER	NO SUCH PARTS	166.30	-
1	FRONT LH SIGNAL LAMP	CRACKED	230.70	230.70
1	FRONT LH "HINO" EMBLEM	NOT NECESSARY	195.00	-
1	FRONT LH "700" EMBLEM	NOT NECESSARY	145.00	-
1	FRONT LH "2041" EMBLEM	NOT NECESSARY	102.00	-
1	FRONT LH WIPER PANEL	CRACKED	1,170.00	1,170.00
	LESS 10% DISCOUNT		-	-546.19
			7,739.20	4,915.67
	<b><u>LABOUR</u></b>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		120.00	20.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC.		800.00	800.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		800.00	800.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		80.00	30.00
			1,800.00	1,650.00
	<b>GRAND TOTAL</b>		<b>9,539.20</b>	<b>6,565.67</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,200.00</b>

Report Ref No. CS/SMO23002982/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.