



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23002982/Uqy3e2 Date: 04/04/2023 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YQ 303R	Veh. Inspected	XD 5235B
	Policy No.	D22MTPCVE001281	Coverage (\$)	0.00
	Claim No.	CMTD2301148/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HINO SH1EERA 13L	c.c	12913
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	SH1EER10027	Colour	WHITE
	Odometer	374772 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	AUSTONE	6 mm
	L/H Front Tyre	295/80 R22.5	AUSTONE	6 mm
	R/H Rear Tyre	295/80 R22.5 (D)	AUSTONE	6/6 mm
	L/H Rear Tyre	295/80 R22.5 (D)	AUSTONE	6/6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	17/03/2023	Inspection Date	22/03/2023
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	