

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23002983/RQP3Q2**Date:** 27/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00152832205		
Claimant Vehicle No :	SMA7905J	Insured Vehicle No :	SJW74Y		
Date of Loss:	20/03/2023	Nature of Claim:	TP	Claim No:	SNM23D202127/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMA7905J</b>	Engine No:	G4FGHH693971
Make & Model:	KIA CERATO K3, 1.6 (A)	Chassis No:	KNAFX411MJ5763907
Reg. Date:	20/06/2018 (Man. Year: 2017)	Odometer:	60419 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,044.00	986.00	1,058.00	51.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	1,630.00	3,520.00	68.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,194.00</b>	<b>2,616.00</b>	<b>4,578.00</b>	<b>63.64</b>
<b>+ GST 8.00/8.00% (S\$)</b>	575.52	209.28	366.24	63.64
<b>Nett Amount (S\$)</b>	<b>7,769.52</b>	<b>2,825.28</b>	<b>4,944.24</b>	<b>63.64</b>

**INSPECTION**

Date of Assignment:	24/03/2023	
Date Inspected:	17/04/2023	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2023)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA7905J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CNC BADGE	Not Necessary	80.00 FS	*- FS
2	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
3	1		*COVER -RR BUMPER	Deformed	651.00 FS	*651.00 FS
4	1		*COVER -RR BUMPER ,CTR	Deformed	315.00 FS	*315.00 FS
5	1		*BEAM -RR BUMPER	Not Necessary	318.00 FS	*- FS
6	1		*BRACKET -RR BEAM LWR MTG	Not Necessary	6.00 FS	*- FS
7	1		*BRACKET -RR BEAM LWR CTR	Obstructed	6.00 FS	*- FS
8	1		*STAY -RR BUMPER LH	Not Necessary	120.00 FS	*- FS
9	1		*STAY -RR BUMPER RH	Not Necessary	120.00 FS	*- FS
10	1		*BRACKET -RR BUMPER SIDE MTG ,LH	Not Necessary	29.00 FS	*- FS
11	1		*BRACKET -RR BUMPER SIDE MTG ,RH	Not Necessary	29.00 FS	*- FS
12	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
13	1		*REVERSE PARKING SENSORS	Not Necessary	250.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,044.00	986.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW RR BUMPER REPAIR END PANEL REPAIR REAR TAILGATE	New	2,560.00	640.00
2	REMOVE AND INSTALL REAR PARKING SENSORS	New	100.00	80.00
3	RESPRAY REAR BUMPER ,REAR END PANEL REAR TAILGATE	New	1,650.00	550.00
4	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	100.00	80.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
6	SUPPLY ANTI CORROSION FOR REAR END PANEL	New	80.00	0.00
7	REMOVE AND REFIT REAR LUGGAGE COMPARTMENT	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>5,150.00</b>	<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >