

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002986/KNY3M4**Date:** 05/04/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG22010440
Claimant Vehicle No :	SLP8552U	Insured Vehicle No :	SME6336L
Date of Loss:	19/03/2023	Nature of Claim:	TP
		Claim No:	CDMPG23000675

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP8552U		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZR595481
Reg. Date:	30/06/2017 (Man. Year: 2016)	Chassis No:	MR053REH104560463
Colour:	Metallic Silver	Odometer:	159586 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,064.09	2,986.90	5,077.19	62.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,220.00	2,420.00	66.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,704.09	4,206.90	7,497.19	64.06
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	11,704.09	3,200.00	8,504.09	72.66
+ GST 8.00/8.00% (S\$)	936.33	256.00	680.33	72.66
Nett Amount (S\$)	12,640.42	3,456.00	9,184.42	72.66

INSPECTION

Date of Assignment:	22/03/2023	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643
Date Inspected:	24/03/2023 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8552U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	680.00 FL	*680.00 FL
2	1		*REAR BUMPER BRACKET LH	Repair	72.20 FL	*- FL
3	1		*REAR BUMPER BRACKET RH	Repair	72.70 FL	*- FL
4	1		*REAR BUMPER REFLECTOR LH	Serviceable	155.60 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Serviceable	155.60 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	67.10 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	67.10 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Bent	498.00 FL	*408.20 FL
9	1		*REAR END PANEL	Repair	780.60 FL	*- FL
10	1		*REAR END PANEL INNER GARNISH	Serviceable	165.00 FL	*- FL
11	1		*TAILLAMP LH	Cut	747.00 FL	*394.50 FL
12	1		*TAILLAMP RH	Serviceable	747.00 FL	*- FL
13	1		*TAILLAMP INNER PANEL LH	Repair	250.00 FL	*- FL
14	1		*TAILLAMP INNER PANEL RH	Repair	250.00 FL	*- FL
15	1		*BOOTLID	Buckled	826.70 FL	*826.70 FL
16	1		*BOOTLID HINGE LH	Repair	155.20 FL	*- FL
17	1		*BOOTLID HINGE RH	Repair	155.20 FL	*- FL
18	1		*BOOTLID WEATHERSTRIP	Serviceable	198.22 FL	*- FL
19	1		*BOOTLICK LOCK	Dented	149.00 FL	*149.00 FL
20	1		*BOOTLID CATCH	Repair	42.00 FL	*- FL
21	1		*BOOTLID EMBLEM - COROLLA	Necessary	68.00 FL	*68.00 FL
22	1		*BOOTLID EMBLEM - ALTIS	Necessary	68.00 FL	*68.00 FL
23	1		*BOOTLID LOGO	Necessary	50.00 FL	*50.00 FL
24	1		*BOOTLID LAMP LH	Cut	529.70 FL	*379.80 FL
25	1		*BOOTLID LAMP RH	Cut	529.70 FL	*379.80 FL
26	1		*BOOTLID OUTER CHROME MOULDING	Serviceable	255.70 FL	*- FL
27	2		*BOOTLID NUMBER PLATE LAMP	Serviceable	136.80 FL	*- FL
28	1		*KEYLESS SENSOR	Cracked	680.00 FL	*185.20 FL
29	1		*SPARE TYRE BOARD	Serviceable	380.00 FL	*- FL
30	1		*REVERSE SENSOR 2PCS WITH HOLDER	Scratched	585.00 FS	*200.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
32	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
33	1		*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*2 SET TAILLAMP PANEL HOLDER	Not Necessary	50.00 FS	*- FS
36	1		*REVERSE CAMERA	Serviceable	380.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
39	1		*REAR WINDSCREEN CLEANER & PRIMER	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					10,297.12	3,884.20
- List Item Discount on L Items 25.00/25.00% (\$\$)					2,233.03	897.30
Total Parts (\$\$)					8,064.09	2,986.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,200.00	550.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,600.00	600.00
3	CHECK WIRING SYSTEM	New	120.00	20.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	120.00	0.00
5	R&R CARPET, INNER TRIM TO ASSIST REPAIR	New	180.00	0.00
6	R&R REVERSE SENSOR & RESETTING	New	120.00	50.00
7	R&R BOOTLID COMPONENTS	New	120.00	0.00
8	R&R REAR WINDSCREEN GLASS	New	180.00	0.00
Gross Labour Cost (S\$)			3,640.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >