

Vehicle Damage Assessment Report for [SLP8552U]

Estimate Created: 01/04/2023 15:09 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 01/04/2023 15:41 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Corolla
Engine Type			
License Plate Number	SLP8552U	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$3,200.00 WITH 4 WORKING DAYS.	Insurlogic 4 (01/04/2023 15:30)
---	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear bumper		1	680.00	-25.00 %	510.00
Rear bumper reinforcement		1	408.20	-25.00 %	306.15
LH tailamp		1	394.50	-25.00 %	295.88
bootlid		1	826.70	-25.00 %	620.03
bootlid lock		1	149.00	-25.00 %	111.75
LH bootlid lamp		1	379.80	-25.00 %	284.85
RH bootlid lamp		1	379.80	-25.00 %	284.85
keyless sensor		1	185.20	-25.00 %	138.90
Bootlid emblem - Corolla		1	68.00	-25.00 %	51.00
Bootlid emblem - Altis		1	68.00	-25.00 %	51.00
Bootlid logo		1	50.00	-25.00 %	37.50

Parts Subtotal 2,691.91

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Reverse sensor with holder		1.0	200.00	0.00 %	200.00
Rear bumper clips (1 set)		1.0	50.00	0.00 %	50.00
Rear number plate		1.0	45.00	0.00 %	45.00

Materials Subtotal 295.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	550.00	0.00 %	550.00
Checking wiring system.	RnR	20.00	0.00 %	20.00
Remove and renew reverse sensor and resetting.	RnR	50.00	0.00 %	50.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
bootlid catch	Medium	0.00	0.00 %	0.00
LH bootlid hinge	Medium	0.00	0.00 %	0.00
LH rear bumper bracket	Medium	0.00	0.00 %	0.00
LH taillamp inner panel	Medium	0.00	0.00 %	0.00
RH bootlid hinge	Medium	0.00	0.00 %	0.00

RH rear bumper bracket	Medium	0.00	0.00 %	0.00
RH taillamp inner panel	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	600.00	0.00 %	600.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	620.00
			Paint Labor Subtotal	600.00
			Labor Subtotal	1,220.00

Summary

Repair Cost	4,206.91
Discount(23 %)	(967.59)
	3,239.32
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,239.32