

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002989/UNY3Q2**Date:** 13/04/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SKR6332C **Insured Vehicle No :** YQ5316X

Date of Loss: 20/03/2023 Nature of Claim: TP Claim No: CDMCG23000685

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR6332C**

Make & Model: VOLKSWAGEN POLO GP, 1.2 TSI ABS D/AIRBAG 2WD 5DR (A) Engine No: CJZ379212

Reg. Date: 26/02/2015 (Man. Year: 2014) Chassis No: WVVZZZ6RZFU041910

Colour: Grey Odometer: 80509 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,564.74	2,883.75	7,680.99	72.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,150.00	2,000.00	63.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,714.74	4,033.75	9,680.99	70.59
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	13,714.74	3,200.00	10,514.74	76.67
+ GST 8.00/8.00% (\$\$)	1,097.18	256.00	841.18	76.67
Nett Amount (\$\$)	14,811.92	3,456.00	11,355.92	76.67

INSPECTION

Date of Assignment: 22/03/2023

Date Inspected: 23/03/2023 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2023)
Parts:	144	VOLKSWAGEN POLO GP 1.2 TSI ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR6332C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	1,459.70 FL	*- FL
2	2		*REAR BOOT LID HINGE	Not Necessary	452.60 FL	*- FL
3	1		*REAR BOOT LID INNER LOCK	Not Necessary	180.90 FL	*- FL
4	1		*REAR BOOT LID INNER BOARD	Not Necessary	294.40 FL	*- FL
5	1		*REAR BOOT LID LOGO	Not Necessary	189.30 FL	*- FL
6	1		*REAR BOOT LID EMBLEM	Not Necessary	68.10 FL	*- FL
7	1		*REAR BOOT LID EMBLEM (BLUE MOTION)	Not Necessary	52.30 FL	*- FL
8	1		*REAR BOOT LID EMBLEM (TSI)	Not Necessary	56.40 FL	*- FL
9	1		*TAIL LAMP	N/S Not Necessary / O/SCracked	837.60 FL	*418.80 FL
10	2		*REAR FENDER INNER GARNISH	Not Necessary	603.80 FL	*- FL
11	2		*REAR TAIL LAMP PANEL	Not Necessary	608.00 FL	*- FL
12	1		*REAR BUMPER	Distorted	1,806.20 FL	*1,432.00 FL
13	1		*REAR BUMPER TOWING COVER	Not Necessary	34.70 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	354.70 FL	*354.70 FL
15	1		*REAR BUMPER CENTRE RETAINER	Cracked	89.10 FL	*89.10 FL
16	2		*REAR BUMPER RETAIN	Not Necessary	99.40 FL	*- FL
17	1		*REAR BUMPER REFLECTOR	N/S Not Necessary/O/SScratched	84.20 FL	*42.10 FL
18	2		*REAR NUMBER LAMP	Not Necessary	71.20 FL	*- FL
19	1		*END PANEL OUTER	Dented / Bent	765.60 FL	*600.80 FL
20	1		*END PANEL INNER	No such part	517.20 FL	*- FL
21	1		*END PANEL GARNISH	Not Necessary	506.20 FL	*- FL
22	1		*SPARE TYRE PANEL COVER BOARD	Not Necessary	581.30 FL	*- FL
23	1		*SPARE TYRE TOOL TRAY SPONGE	Not Necessary	111.60 FL	*- FL
24	1		*REAR EXHAUST PIPE	Repair	1,106.30 FL	*- FL
25	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	143.40 FL	*- FL
26	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	114.40 FL	*- FL
27	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*40.00 FS
28	1		*SET REVERSING SENSOR	Malfunction	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,683.60	3,177.50
- List Item Discount on L Items 10.00/10.00% (S\$)	1,118.86	293.75
Total Parts (S\$)	10,564.74	2,883.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET FAL COVER	New	150.00	20.00
2	TUFF KOTE	New	250.00	30.00
3	TO REMOVE REPLACE SPARE PART AND PANEL BEATING	New	1,200.00	550.00
4	TO SPRAY PAINTING	New	1,000.00	500.00
5	REMOVE REFIX REVERSING SENSOR	New	150.00	50.00
6	REMOVE REFIX REAR BOOT TRIMMING ETC	New	250.00	0.00
7	REMOVE REFIX EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,150.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >