



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD  
CO. REG. No.: 1995-01140-D

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002443195-01	Date of Loss:	21/03/2023
Vehicle Reg. No.:	<b>SKR6070H</b>	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RYAN KIM TIAN WOON	Contact No:	+6590239755
Driver:	RYAN KIM TIAN WOON		
Make/Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Vehicle Reg. Date:	23/02/2015
Vehicle Colour:	GREY		
Engine No:	27091030543349	Chassis No:	WDD1173422N158517
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	6		
Remarks:	VEHICLE IN WORKSHOP		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	4,235.80
Miscellaneous Items	0.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>5,785.80</b>
<b>+ GST 8.00% (S\$)</b>	<b>462.86</b>
<b>Nett Amount (S\$)</b>	<b>6,248.66</b>

This claim is handled by: **JOSHUA NG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 22 Mar 2023)

**Parts:** 143      MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** Falcon-Air Auto Services Pte Ltd/SKR6070H/22/03/2023 15:29

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*1,400.00 F
2	1		*O/S FRONT BUMPER BRACKET	0.00	0.00	*28.00 F
3	10		*FRONT BUMPER CLIPS	0	0.00	*40.00 FS
4	10		*FRONT BUMPER RIVET	0	0.00	*40.00 FS
5	1		*O/S FRONT FENDER	0.00	0.00	*600.00 F
6	1		*O/S HEADLAMP	0.00	0.00	*1,750.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>3,858.00</b>
<b>+ Margin on L,N Items 10.00% (S\$)</b>	<b>377.80</b>
<b>Total Parts (S\$)</b>	<b>4,235.80</b>

Falcon-Air Auto Services Pte Ltd/SKR6070H/22/03/2023 15:29. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO CHECK WIRING	New	50.00
2	TO RE-PROGRAMME HEADLAMP MODULE	New	300.00
3	TO REMOVE NECESSARY PARTS TO REPAIR INNER PANEL, REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	600.00
4	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	600.00
<b>Gross Labour Cost (S\$)</b>			<b>1,550.00</b>

Falcon-Air Auto Services Pte Ltd/SKR6070H/22/03/2023 15:29. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**FALCON-AIR AUTO SERVICES PTE LTD**  
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862  
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg