

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23002990/HVY3E2**Date:** 17/04/2023REFERENCE

Insured/Claimant:	RYAN KIM TIAN WOON	Policy No:	SP2002443195-01
Date of Loss:	21/03/2023	Nature of Claim:	OD
		Claim No:	202332006371

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR6070H	Engine No:	27091030543349
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Chassis No:	WDD1173422N158517
Reg. Date:	23/02/2015 (Man. Year: 2014)	Odometer:	137064 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,477.80	4,437.80	40.00	0.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,180.00	370.00	23.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,027.80	5,617.80	410.00	6.80
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	6,027.80	5,017.80	1,010.00	16.76
+ GST 8.00/8.00% (S\$)	482.22	401.42	80.80	16.76
Nett Amount (S\$)	6,510.02	5,419.22	1,090.80	16.76

INSPECTION

Date of Assignment:	22/03/2023	Present Location:	Falcon-Air Auto Services Pte Ltd (Tampines) Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected:	23/03/2023	Inspected At:	Blk 9006 #01-200 Tampines St 93 Singapore 528840
Estimated Period of Repair:	4.0 days		

Adjuster: Edward**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2023)
Parts: 143	MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKR6070H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cut	1,400.00 F	*1,400.00 F
2	1		*O/S FRONT BUMPER BRACKET (WCP)	Dented	28.00 F	*28.00 F
3	10		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
4	10		*FRONT BUMPER RIVET	Not Necessary	40.00 FS	*- FS
5	1		*O/S FRONT FENDER (WCP)	Buckled	600.00 F	*600.00 F
6	1		*O/S HEADLAMP (WCP)	Broken	1,750.00 F	*1,750.00 F
Supplementary #1						
7	1		*FRONT BUMPER LOGO EMBLEM (WCP)	Necessary	60.00 F	*60.00 F
8	1		*FRONT BUMPER BASIC CARRIER (WCP)	Cracked	160.00 F	*160.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,078.00	4,038.00
+ Margin on L,N Items 10.00/10.00% (S\$)	399.80	399.80
Total Parts (S\$)	4,477.80	4,437.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO RE-PROGRAMME HEADLAMP MODULE	New	300.00	150.00
3	TO REMOVE NECESSARY PARTS TO REPAIR INNER PANEL, REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	600.00	400.00
4	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	600.00	600.00
			Gross Labour Cost (\$)	1,550.00
				1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >