



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002443195-01	Date of Loss:	21/03/2023
Vehicle Reg. No.:	SKR6070H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RYAN KIM TIAN WOON	Contact No:	+6590239755
Driver:	RYAN KIM TIAN WOON		
Make/Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Vehicle Reg. Date:	23/02/2015
Vehicle Colour:	GREY		
Engine No:	27091030543349	Chassis No:	WDD1173422N158517
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8.4		
Remarks:	VEHICLE IN WORKSHOP		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

COST OF CLAIMS	Amount
Parts	4,235.80
Miscellaneous Items	0.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,785.80
+ GST 8.00% (S\$)	462.86
Nett Amount (S\$)	6,248.66

This claim is handled by: JOSHUA NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts: 143 MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SKR6070H/22/03/2023 15:29
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*1,400.00 F, <i>cut</i>
2	1		*O/S FRONT BUMPER BRACKET	0.00	0.00	*28.00 F, <i>DT</i>
3	10		*FRONT BUMPER CLIPS	0	0.00	*40.00 FS, <i>NEC</i>
4	10		*FRONT BUMPER RIVET	0	0.00	*40.00 FS <i>→</i>
5	1		*O/S FRONT FENDER	0.00	0.00	*600.00 F, <i>Buc</i>
6	1		*O/S HEADLAMP	0.00	0.00	*1,750.00 F, <i>BR</i>
Sub Total (S\$)						3,858.00
+ Margin on L,N Items 10.00% (S\$)						377.80
Total Parts (S\$)						4,235.80

F=Franchise part. S=SpocNett.

Falcon-Air Auto Services Pte Ltd/SKR6070H/22/03/2023 15:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING	New	30 50.00 ✓
2	TO RE-PROGRAMME HEADLAMP MODULE	New	150 300.00 ✓
3	TO REMOVE NECESSARY PARTS TO REPAIR INNER PANEL, REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	400 600.00 ✓
4	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	400 600.00 ✓
Gross Labour Cost (S\$)			1,550.00

Falcon-Air Auto Services Pte Ltd/SKR6070H/22/03/2023 15:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 4 DAYS

FALCON-AIR AUTO SERVICES PTE LTD (a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 83 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5685 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

- NOT AUTHORISE
- EXCESS \$ 600
- P/P OR L/S REPAIR?
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: