

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS23002991/UVY3M4**Date:** 03/04/2023**REFERENCE**

Insured/Claimant: SIAH CHEE KIAN (XIE ZHIJIAN) Policy No: MPC22A00169800
Date of Loss: 21/03/2023 Nature of Claim: OD Claim No: DMPC2300197H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB3438A**
Make & Model: VOLKSWAGEN GOLF, 1.4 TSI CL (A) Engine No: CZC996796
Reg. Date: 16/11/2018 (Man. Year: 2018) Chassis No: WVWZZZAUZKW014945
Colour: Red Odometer: 62850 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,365.10	8,773.60	3,591.50	29.05
Miscellaneous Items	65.00	65.00	0.00	0.00
Labour	1,730.00	1,520.00	210.00	12.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,160.10	10,358.60	3,801.50	26.85
+ GST 8.00/8.00% (S\$)	1,132.81	828.69	304.12	26.85
Nett Amount (S\$)	15,292.91	11,187.29	4,105.62	26.85

INSPECTION

Date of Assignment: 22/03/2023 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 23/03/2023 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
Estimated Period of Repair: 5.0 days 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,118.50 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts:	144	VOLKSWAGEN GOLF 1.4 TSI CL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB3438A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Buckled	980.00 F	*980.00 F
2	2		*FRT BONNET HINGE (WCP)	Bent	190.00 F	*190.00 F
3	1		*FRT BONNET LOCK (WCP)	Bent	195.00 F	*195.00 F
4	1		*FRT BONNET LOCK CATCH (WCP)	Not Necessary	80.00 F	*- F
5	1		*FRT GRILLE (WCP)	Broken	330.00 F	*330.00 F
6	1		*FRT GRILLE CENTER LOGO (WCP)	Broken	85.00 F	*85.00 F
7	4		*FRT GRILLE CLIP (WCP)	Necessary	16.00 F	*16.00 F
8	1		*FRT BUMPER NO STOCK (WCP)	Distorted	1,450.00 F	*1,450.00 F
9	2		*FRT BUMPER RETAINER (WCP)	Bent	70.00 F	*70.00 F
10	10		*FRT BUMPER CLIP (WCP)	Necessary	40.00 F	*40.00 F
11	1		*FRT BUMPER INNER SPONGE (WCP)	* Check	65.00 F	*- F
12	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	395.00 F	*395.00 F
13	1		*RH HEADLAMP NOOZLE NO STOCK (WCP)	* Check	220.00 F	*- F
14	1		*RH HEADLAMP NOOZLE COVER NO STOCK (WCP)	Missing	65.00 F	*65.00 F
15	2		*HEADLAMP (WCP)	Cracked	2,900.00 F	*2,900.00 F
16	2		*HEADLAMP PANEL (WCP)	Buckled	150.00 F	*150.00 F
17	1		*HEADLAMP SUPPORT PANEL (WCP)	* Check	650.00 F	*- F
18	1		*BRACE PANEL (WCP)	Bent	75.00 F	*75.00 F
19	1		*AIRCON CONDENSER (WCP)	Bent/Punctured	395.00 F	*395.00 F
20	1		*RADIATOR (WCP)	* Check	340.00 F	*- F
21	1		*INTERCOOLER (WCP)	* Check	370.00 F	*- F
22	1		*RADIATOR MOTOR ASSY (WCP)	* Check	800.00 F	*- F
23	1		*FRT FENDER NO STOCK (WCP)	N/s Repair/ O/s Bent/Buckled	700.00 F	*350.00 F
24	2		*FRT WINDSCREEN SIDE TRIM NO STOCK (WCP)	* Check	390.00 F	*- F
25	2		*FRT BUMPER PARKING SENSOR (WCP)	Malfunction	290.00 F	*290.00 F

F=Franchise part.

Sub Total (\$\$)				11,241.00	7,976.00
+ Margin on L,N Items 10.00/10.00% (\$\$)				1,124.10	797.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					12,365.10	8,773.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NUMBER PLATE (SCRATCHED)	40.00	40.00
2	1	RADIATOR COOLANT (NECESSARY)	25.00	25.00
Sub Total (S\$)			65.00	65.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	LABOUR CHARGE	New	700.00	600.00
4	SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (S\$)			1,730.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >